



**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA
CAWANGAN PERAK
KAMPUS SERI ISKANDAR**

**DEFECT INSPECTION DURING DEFECT LIABILITY PERIOD :
HOUSING PROJECT ELVINA TYPE AT BANDAR SRI SENDAYAN**

**MUHAMMAD SHAFFI BIN ABDOL JOHAR
(2015814916)
DIPLOMA IN BUILDING SURVEYING**

**PRACTICAL TRAINING REPORT
MARCH – JULY 2018**

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:



.....
(MUHAMMAD SHAFFI)

Date: 2 . 7 . 2018

Approved By:



.....
(Sr. AMIR FASHA)

Date: 2 . 7 . 2018

AMIR FASHA BIN MOHD ISA
Pensyarah
Jabatan Ukur Bangunan
FSPU
Universiti Teknologi MARA (Perak)

CONTENTS

TABLE OF CONTENT	i
ACKNOWLEDGEMENT	iii
LIST OF FIGURES	iv
LIST OF TABLES	vi
LIST OF CHART	vii
1.0 INTRODUCTION	1
1.1 Company Background	2
1.1.1 View of The Building	6
1.1.2 Adjacent Building	7
1.2 Vision, Mission and Quality Policy	8
1.3 Organization Chart	11
1.4 Scope of Work	12
1.5 Location Plan	14
1.6 Training Description	17
1.6.1 Customer Service Department Organization Chart	18
1.6.2 View of The Building	19
1.6.3 Adjacent Building	20
1.7 Completed Project and On-Going Project	22
1.7.1 Completed Project	22
1.7.2 On-Going Project	27
1.8 Summary	29
2.0 THEORETICAL STUDY / LITERATURE REVIEW	
2.1 Introduction of Defect Liability Period	30
2.2 Defect Inspection During Defect Liability Period	31
2.3 Clause Related To Defect Liability Period	32
2.3.1 Obligation of Consultant	33
2.3.2 Obligation of Contractor	33
2.3.3 Obligation of Owner	33
2.4 Purpose of Defect Liability Inspection	35
2.4.1 Maintenance and Rectification of Defects	35
2.5 Extension of Defect Liability Period	36

ACKNOWLEDGEMENT

Firstly, special thanks to our dedicated subject lecturer, Sir Sr Mohd Nurfaizal Baharuddin, who is the program coordinator for BSR 360. The given knowledge and guidance of preparing the report is such a valuable experience for me.

The highest and sincerest thankful to our dedicated and experienced supervisor Sr Amir Fasha, who has given the valuable guidance during the completion of the report and throughout the practical program.

Special gratitude to the Matrix Care Centre, Eddie Bin Zakaria as the Assistant Manager and the other staff for the best cooperation by providing the valuable information regarding on my case of study for project Hijayu 3B Elvina.

Not to be forgotten, the precious cooperation and help during the preparation and completion of the report and presentation. The report would remain incomplete without the great help from Adib Hizami and Mohamad Radhuan as my trainee member at Customer Service Department.

Lastly, thank you to the direct and indirect involvement of other classmates who has also provide the help and keep giving the necessary information for the completion of the report.

LIST OF FIGURES

FIGURE	DESCRIPTION	PAGE
CHAPTER 1		
1.1	Matrix Concept Holding Berhad Logo	2
1.2	Side View of Matrix Concept Holding Berhad	6
1.3	Front View of Matrix Concept Holding Berhad	6
1.4	Quality Policy	9
1.5	Key Plan of Malaysia	14
1.6	Key Plan of Negeri Sembilan	14
1.7	Key Plan of Seremban	15
1.8	Location Plan of Matrix Concept Holding Berhad	15
1.9	Site Plan of Bandar Sri Sendayan	16
2.0	View of d'Tempat Clubhouse	19
2.1	Front View of Matrix Care Centre Office	19
CHAPTER 2		
-		
CHAPTER 3		
2.2	Site Plan of HIjayu 3B Elvina	44
2.3	Intermediate Floor Plan of Hijayu 3B Elvina	45
2.4	End Lot Floor Plan of Hijayu 3B Elvina	46
2.5	Corner Lot Floor Plan of Hijayu 3B Elvina	47
2.6	Top View of Hijayu 3B Elvina 23	49
2.7	Front View of Hijayu 3B Elvina 23	50
2.8	Rear View of Hijayu 3B Elvina 23	50
2.9	Defect Notification Form	55
3.0	Defect Notification Form	56
3.1	Customer Service Defect Reporting Menu	57
3.2	Customer Service Defect Management New	58
3.3	Outstanding DNF Detail Aging Report	59
3.4	Rectification Works on Hollowness of Tiles	61
3.5	Rectification Works on Crack of Plaster on Wall	61
3.6	Rectification Works on Master Bathroom Water Leakage	62
3.7	Installation of Floor Tiles at Master Bedroom	62
3.8	Notice of Completion Rectification	64
3.9	Joint Inspection With The Contractor	66
4.0	Rectified Defect in The Unit	66
4.1	Notice of Completion	68
CHAPTER 4		
-		