



اَوْنُوْرَسِيْتِي تِكْنُوْلُوْجِي مَارَا  
UNIVERSITI  
TEKNOLOGI  
MARA

**DEPARTMENT OF BUILDING SURVEYING  
FACULTY OF ARCHITECTURE, PLANNING AND  
SURVEYING  
UNIVERSITI TEKNOLOGI MARA**

**CASE STUDY:  
INSPECTION FOR DEFECTS AT BOARDING  
BUILDING AT SMK SULTAN MUHAMMAD SHAH,  
PARIT PERAK**

**ADILYNNE ENDAU KANEDDY  
2011281174  
DIPLOMA IN BUILDING SURVEYING**

**PRACTICAL TRAINING REPORT  
DECEMBER 2013 – MARCH 2014**

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....

(ADILYNNE ENDAU KANEDDY)

Date: 14/03/2014

Approved By:

.....

(PUAN SITI ZUBAIDAH BINTI HASHIM)

Date: 14/03/2014

## TABLE OF CONTENT

No.	Content	Page
<b>1</b>	<b>ACKNOWLEDGEMENT</b>	ii
<b>2</b>	<b>LIST OF FIGURES</b>	iii
<b>3</b>	<b>LIST OF TABLES</b>	iii
<b>4</b>	<b>CHAPTER 1 INTRODUCTION</b> 1.1 Company background / profile 1.2 Vision and mission 1.3 Organization chart Administration Department Road Department Maintenance Department Building Department 1.4 Objective of company 1.5 Location plan	 1-2 3 4-7  8 9
<b>5</b>	<b>CHAPTER 2 THEORETICAL STUDY / LITERATURE REVIEW</b> 2.1 Introduction of Maintenance 2.2 Definition of Maintenance 2.3 Type of Maintenance 2.4 Method Statement	 11 12-13 14-19 20
<b>6</b>	<b>CHAPTER 3 CASE STUDY</b> 3.1 Introduction to Case Study 3.2 Objectives of Inspection 3.3 Project background 3.4 Inspection methodology 3.5 Inspection and observation result	 21 22 23 24 25-35
<b>7</b>	<b>CHAPTER 4 PROBLEM AND RECOMMENDATION</b> 4.1 Problem and Recommendation	 36
<b>8</b>	<b>CHAPTER 5 CONCLUSION</b>	37
<b>9</b>	<b>CHAPTER 6 REFERENCES</b>	38

## **ACKNOWLEDGEMENT**

I take this opportunity to express my profound gratitude and deep regards to my guide Puan Siti Zubaidah Binti Hashim for her exemplary guidance, monitoring and constant encouragement throughout the course of this practical report. The blessing, help and guidance given by her time to time shall carry me a long way in the journey of life on which I am about to embark.

I also take this opportunity to express a deep sense of gratitude to Miss Zaina Haiza engineer of the maintenance department, JKR Perak Tengah, for her cordial support, valuable information and guidance, which helped me in completing this task through various stages.

I am obliged to staff members of JKR Perak Tengah especially Puan Azizah the technician of the maintenance department, for the valuable information provided by them in their respective fields. I am grateful for their cooperation during the period of my practical training.

Lastly, I thank my parents, brother, sisters and friends for their constant encouragement without which this practical training report would not be possible.

## **LIST OF FIGURES**

- i.** Figure 1.1 JKR Perak Tengah
- ii.** Figure 1.2 Site plan of JKR Perak Tengah
- iii.** Figure 3.1 SMK Sultan Muhammad Shah
- iv.** Figure 3.5.1 Water mark on the wall and ceiling
- v.** Figure 3.5.2 Stalactite formation
- vi.** Figure 3.5.3 Patching work using gypsum board
- vii.** Figure 3.5.4 Unsuitable patch materials
- viii.** Figure 3.5.5 Broken floor plaster

## **LIST OF TABLES**

- i.** Table 1.0 Company profile
- ii.** Table 1.1 Administration department chart
- iii.** Table 1.2 Road department chart
- iv.** Table 1.3 Maintenance department chart
- v.** Table 1.4 Building department chart
- vi.** Table 2.1 Types of maintenance