



DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA
CAWANGAN PERAK
KAMPUS SERI ISKANDAR

INTERGRATED FINAL PROJECT (BSR330)

CASE STUDY:

Menara Tabung Haji Ipoh

PREPARED BY:

NICHOLAS EGAT ANAK MENARI	2014535023
MOHD AZLAN BIN JAWAL	2014992043
MOHD REDZUAN BIN MUSI	2014373427
NURSYUHADA BINTI ROZALI	2014524317
NURUL AIN BINTI YAHYA@YAHAYA	2014931657

DIPLOMA IN BUILDING SURVEYING

**SEMESTER
DECEMBER 2016 – MARCH 2017**

TABLE OF CONTENT

TABLE OF CONTENT	i
TABLE OF SCHEDULE	vi
TABLE OF PHOTO.....	xi
TABLE OF FIGURE.....	xvi
1.0 THE DETAILS OF PROPERTY	1
1.1 INTRODUCTION.....	1
1.2 BUILDING BACKGROUND	2
1.2.1 Property Summary Detail.....	2
1.2.2 Mission and Objective.....	3
1.2.3 Building View	6
1.2.4 Adjacent Building.....	7
1.2.5 Key plan, Location and Site Plan.....	9
1.3 PROJECT BRIEF.....	11
1.4 LIST OF MAJOR OCCUPANTS / TENANTS.....	15
1.4.1 Space Usage.....	16
1.5 FACILITIES AND BUILDING SERVICES.....	19
1.6 SUMMARY	23
2.0 ORGANIZATIONAL MAINTENANCE MANAGEMENT.....	24
2.1 INTRODUCTION.....	24
2.2 ORGANIZATION OBJECTIVE	24
2.2.1 Vision:	24
2.2.2 Mission:	24
2.2.3 Tabung Haji Ipoh Organization Objective	24
2.2.4 Tabung Haji Ipoh Maintenance Objective	25
2.3 MAINTENANCE ORGANIZATIONAL STRUCTURE	26
2.4 SCOPE OF WORK AND RESPONSIBILITIES	27
2.5 SUMMARY	28
3.0 MAINTENANCE POLICY, PLANNING AND PROGRAMME.....	29



TABLE OF SCHEDULE

NO.	ITEMS	PAGES
1	Table 1.1: Property Summary Detail	3
2	Table 1.2: Organization Chart	5
3	Table 1.3: Project Brief	13
4	Table 1.4: Project Brief (Renovation Process)	14
5	Table 1.5: List of Major Occupants / Tenants	16
6	Table 1.6: List of major tenants	18
7	Table 1.7: Facilities and Building Services	22
8	Table 2.1: Scope of work and responsibility	27
9	Table 3.1: Scope of work	31
10	Table 3.2: Daily Checking & Maintenance	32
11	Table 3.3: Weekly Checking & Maintenance	33
12	Table 3.4: Monthly Checking & Maintenance	34
13	Table 3.5: Half Yearly Checking & Maintenance	36
14	Table 3.6: Yearly Checking & Maintenance	37
15	Table 3.7: Scope of Work	40
16	Table 3.8: Response for Repairing Work	46
17	Table 3.9: Civil & Structure Schedule	48
18	Table 3.10: Electrical Schedule	48
19	Table 3.11: Mechanical Schedule	50
20	Table 3.12: Housekeeping for Office Space	50
21	Table 3.13: Housekeeping for Common Area Schedule	50



TABLE OF PHOTO

NO.	ITEMS	PAGES
1	Photo 1.1: Bangunan Tabung Haji Ipoh	2
2	Photo 1.2: Front Elevation	6
3	Photo 1.3: Right Elevation	6
4	Photo 1.4: Left Elevation	7
5	Photo 1.5: Rear Elevation	7
6	Photo 1.6: Jabatan Kesihatan Negeri	8
7	Photo 1.7: Police station	8
8	Photo 1.8: Shop lot	8
9	Photo 1.9: Jabatan Kebajikan Masyarakat Negeri	9
10	Photo 1.10 : Basement	19
11	Photo 1.11: Toilets	19
12	Photo 1.12 : Surau	20
13	Photo 1.13 : CCTV	20
14	Photo 1.14: Fire-fighting system	20
15	Photo 1.15 : Elevators / lift	21
16	Photo 1.16 : ATM Machine	21
17	Photo 1.17 : Information Counter	22
18	Photo 1.18 : Waiting Area	22
19	Photo 3.1: Tabung Haji Complain Form	47
20	Photo 4.1: Tabung Haji Ipoh	55
21	Photo 4.2: Basement	58
22	Photo 4.3: Column	58
23	Photo 4.4: Beam	58
24	Photo 4.5: Internal	59
25	Photo 4.6: External	59
26	Photo 4.7: Windows	59



TABLE OF FIGURE

NO.	ITEMS	PAGES
1	Figure 1.1: Maps of Perak	9
2	Figure 1.2: Location of Ipoh , Perak	10
3	Figure 1.3: Location of Pejabat Tabung Haji Ipoh	10
4	Figure 1.4: Lembaga Tabung Haji	11
5	Figure 1.5: Hajeedar & Associates	11
6	Figure 1.6: Associated Builders & Contractors	11
7	Figure 1.7: Berakan Jurutera Perunding Sdn.Bhd	12
8	Figure 1.8: Jentrik Sdn.Bhd	12
9	Figure 1.9: Juru Ukur Bahan Malaysia Wisma JUBM	12
10	Figure 1.10: A.M.S Engineering Sdn.Bhd	13
11	Figure 1.11: S.Azlan Architect	13
12	Figure 1.12: Skala Design Consult Sdn.Bhd	14
13	Figure 1.13: Perunding JYS Sdn.Bhd	14
14	Figure 1.14: ZARY associates	14
15	Figure 4.1: View from above	56
16	Figure 4.2: Honeycomb concept	57
17	Figure 4.3: Position of soil stack pipe	65
18	Figure 4.4: Electrical Distribution System	68
19	Figure 5.1: Defect Analysis by Defect	101
20	Figure 5.2: Defect Analysis by Area	102
21	Figure 5.3: Defect Analysis by Element	103
22	Figure 5.4: Defect Indication for Level 1	159