CENTRE OF STUDIES FOR BUILDING SURVEYING FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING UNIVERSITI TEKNOLOGI MARA

A STUDY ON DAMPNESS DEFECT IN GOVERNMENT QUARTERS IN THREE DIFFERENT AREAS (URBAN, COASTAL AND HIGHLAND)

MOHAMMAD FAIZ BIN AB HALIM (2011170255)

Academic Project submitted in partial fulfillment of the requirements for the degree of Bachelor of Building Surveying (Hons) Centre of Studies for Building Surveying Faculty of Architecture, Planning & Surveying

December 2013

CENTRE OF STUDIES FOR BUILDING SURVEYING FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING UNIVERSITI TEKNOLOGI MARA

A STUDY ON DAMPNESS DEFECT IN GOVERNMENT QUARTERS IN THREE DIFFERENT AREAS (URBAN, COASTAL AND HIGHLAND)

"I hereby declare that this academic project is the result of my own research except for the quotation and summary which have been acknowledged"


Student's Name	: Mohammad Faiz Bin Ab Halim
Signature	· Janz
UITM No.	: 2011170255
Date	: January 27 th 2014

CENTRE OF STUDIES FOR BUILDING SURVEYING FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING UNIVERSITI TEKNOLOGI MARA

ACADEMIC PROJECT BSS 608 & BSS 658

CONFIRMATION OF ACADEMIC PROJECT AMENDMENTS

This is to confirm that the student has amended his/her academic project as directed and therefore allowed to compiles



ABSTRACT

Dampness is one of the defects that commonly occur at all types of building. The dampness defect is usually causes by the excessive quantity of moisture of moisture inside the building. It will cause a bad internal and external environment condition which can lead to building deterioration. This study will be describe on the dampness defect that occurs at the government building in three different area which is Shah Alam (Urban), Kuantan (Coastal) and Cameron Highlands (Highland). The purpose of this study is to investigate the causes of dampness that occur at each area selected and to compare the characteristics of the dampness defect based on visual inspection. This study focused at the government quarters at different areas where the weather condition of each area probably lead to different causes and types of dampness defect. From the analysis of dampness defect at the three areas that has been carried out, the type of dampness that is occurs is different at each area. The most dampness defect occurs at the urban is mold growth. However, there is a dampness defect that that only occurs at coastal area which is hygroscopic salt. And the most dampness defect occur at highland area is mold growth and discolouration. The dampness problems at each area need a remedial and repairing work such as removing of the mold growth. All the building needs a proper maintenance in order to maintain the condition and performance of the building.

ACKNOWLEDGEMENT

Hereby, I am so grateful and thankful to those who have given hands and help me during preparation of this Academic Project. First and foremost, my greatest gratitude and thankful is dedicated to **Sr. Hikmah Kamarudin** as my lecturer supervisor for her knowledge and advices. I had gained lot guidance from her.

I would also like to express thanks to the **Maintenance Departments** from all Government Quarters involved because give permission to carried out inspection at the building and spend their time for the interview session. There are many useful data and information that is given by them.

But from all of the above mentioned, my endless thanks and love will definitely specially dedicated to dearest **family** who has given such a tremendous and endless support and encouragement. Not forgotten to my entire **classmate** that given a support.

Last but not least, I hope that i can use all the knowledge and experience that has been gained from this Academic Project while working.

ii