

THE DOCTORAL RESEARCH ABSTRACTS

Volume: 5, Issue 5 May 2014



INSTITUTE of GRADUATE STUDIES

Leading You To Greater Heights, Degree by Degree

IPSis Biannual Publication

Name:

Che Mohamad Som Bin Said

Title

Failure Of Thick Rubber Vulcanizates By Blowout

Faculty:

Applied Science

Supervisor:

Prof. Dr. Hj Azemi Samsuri (MS)

Dr. Alias Othman (CS)

One of the premature failures of truck and bus tyres is associated with temperature rise known as blowout that occurs in the thick shoulder regions of the tyre. It occurs due to various dissipative processes under dynamic deformations. The heat produced is sufficiently high to cause thermal degradation that produces volatiles, which consequently exerts internal pressure sufficiently large to tear open a path to the exterior. Blowout failure may cause fatal road accidents. Although the tyre industry is aware of the problem, research in this area is still inadequate apart from the work conducted by Gent and Hindi in 1988, Choi and Kim in 1998 and Park in 2000. The factors affecting heat generation are still not fully investigated, thus the work presented in this thesis has covered the areas which are not covered by the previous researchers. This includes the work to investigate the effects of glass-transition temperature, Ta of the rubber, particle size of the filler, structure of filler, viscosity of process oil and coupling agent on silicafilled vulcanizate on temperature rise and blowout failure. Temperature rise and blowout failure tests were conducted by subjecting a cylindrical testpiece to flexing in a compression flexometer at a constant displacement amplitude in accord with ISO466/3-1982. The compression flexometer was modified accordingly to monitor the temperature rise in the interior of the test-piece continuously until the occurrence of blowout failure. Thus this enables the true blowout temperature to be registered. Some of the interesting findings are highlighted in this abstract. In unfilled vulcanized rubber, the temperature rise was found to increase in the increasing order of the Tg of the rubber, NBR>SBR>NR. However, the heat produced was not sufficiently high to cause blowout failure because the heat generated by mechanical work was not sufficiently high either to cause degradation of rubber or to cause breaking of chemical crosslink. In black-filled vulcanizates, temperature rise and blowout were affected by the Tg of the rubber, filler loading, particle size and filler structure. Increasing the Tg, filler loading, filler structure and decreasing the particle size increased temperature rise and shortened the blowout time. The blowout failure was also affected by the process oil. Blowout time was shorter with paraffinic oil than aromatic oil. In the case of silica-filled vulcanized rubber, temperature rise and blowout temperature increased with increasing amount of coupling agent (TESPT) beacuse the hardness increased progressively with increasing TESPT and hence higher dynamic work was required to deform the test-piece at a constant displacement amplitude. The results show that the actual blowout temperature was much higher than the temperature recorded at the base of the testpiece. The blowout temperature of the interior of the test-piece was 200oC for NR and 230 - 240oC for NBR and SBR respectively. These actual blowout temperatures are in good agreement with those reported independently by Gent and Hindi, and that of Choi and Kim.