

**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA**

A STUDY ON VENTILATION SYSTEM AT OFFICE BUILDING

**NURSYIDA BINTI ZAINOL ABIDIN
2006131239
BACHELOR OF BUILDING SURVEYING**

OKTOBER 2009

ABSTRACT

The ventilation system types in office buildings related with sick building syndrome. this significantly caused of inadequate of ventilation system in the building. Commercial building like office building are more applying on mechanical ventilation compared to the residential. Many types of air-conditioning system that applies in office building. The technology of air conditioning system provided such as Building Automation System compared with the operation manual give more frequency of problems and defect that are give the impact to building performance. Also impact to the occupant health, environment and economics.

LIST OF CONTENT

	Page
ACKNOWLEDGMENT	i
ABSTRACT	ii
CHAPTER 1 INTRODUCTION	1
1.1 PREFACE	1
1.2 PROBLEM STATEMENT	2
1.3 OBJECTIVE OF THE STUDY	3
1.4 SCOPE OF STUDY	3
1.5 METHODOLOGY	4
1.5.1 Summary of Methodology	5
CHAPTER 2 VENTILATION SYSTEM	
2.0 INTRODUCTION	6
2.1 TYPES OF VENTILATION SYSTEMS	
2.1.1 Natural Ventilation	7
2.1.2 Mechanical Ventilation	7
2.2 MECHANICAL VENTILATION IN COMMERCIAL BUILDING	8
2.3 HVAC COMPONENTS SYSTEM	
2.3.1 Air and ducts	8
2.3.2 Pumps and valve	9
2.3.3 Water Distribution Systems	10
2.3.4 Chillers	11
2.3.5 Cooling Tower	13

2.3.6	Fans and Dampers	14
2.3.7	Air-Handling Units	15

CHAPTER 3 SICK BUILDING SYNDROME SBS

3.0	INTRODUCTION	17
3.1	DEFINITIONS	18
3.1.1	Criticism of the SBS definition	18
3.2	CAUSES OF SICK BUILDING SYNDROME	19
3.2.1	Ventilation	20
3.2.2	Water / Moisture / Humidity	20
3.2.3	Volatile Organic Compounds (VOC)	20
3.2.4	Psychosocial factors	21
3.3	INDOOR AIR QUALITY	21
3.3.1	Basics Of Indoor Air Quality	21
3.3.2	Elements Of Indoor Air Quality	22

CHAPTER 4 CASE STUDIES

4.0	INTRODUCTION	24
4.1	MENARA TUN RAZAK	25
4.1.1	System Description	26
4.1.2	Centralized Plant System	26
4.1.3	Water and Air Cooled Package unit	29
4.2	MENARA BUMIPUTRA, BANK MUAMALAT	30
4.2.1	System Description	31
4.2.2	Centralized Plant System	31
4.2.3	Air Cooled Chiller	34

4.3	QUILL 7	36
4.3.1	System Description	37
4.3.2	Centralized Plant System	40
4.3.3	Gas District cooling System	44

CHAPTER 5 ANALYSIS AND FINDINGS

5.0 INTRODUCTION

5.1 SECTION A: INDOOR AIR QUALITY

5.1.1	Percentage of respondents on working period in the building	46
5.1.2	Percentage of respondents on total hour per day spent in the building	47
5.1.3	Number of respondents on uncomfortable feeling of workspace	48
5.1.4	Percentage of respondents on their complaint to maintenance department	49
5.1.5	Number of respondents on physical symptoms while working	50
5.1.6	Percentage of respondents on problems occurs	53
5.1.7	Percentage of respondents on do the symptoms clear	54
5.1.8	Percentage of respondents on taking medication	55
5.1.9	Percentage of respondents on smoking	56
5.1.10	Percentage of respondents on did others smoking	57

5.2 SECTION B: PROBLEMS IN COMPONENT OF THE SYSTEM

5.2.1	Case Study 1: Menara Tun Razak	58
5.2.2	Case Study 2: Menara Bumiputra	60
5.2.3	Case Study 3: Quill 7	61

5.3 SECTION C: MAINTENANCE MANAGEMENT **63**