



**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA
CAWANGAN PERAK
KAMPUS SERI ISKANDAR**

**PREVENTIVE MAINTENANCE AND ADHOC CORRECTIVE IN MENARA TABUNG
HAJI TUN RAZAK**


**SHAFIYAH BT WAN MD SUHAIMI
2015822592
DIPLOMA IN BUILDING SURVEYING**

**PRACTICAL TRAINING REPORT
MARCH – JULY 2018**

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:



.....
Shafiyah Bt Wan MdSuhaimi

Date: 4/7/2018

Approved By:



.....
Puan Zurahana Ahmad Zawawi

Date: 3/7/2018

ACKNOWLEDGMENT

I would like to express my gratitude and appreciation to all those who gave possibility to complete this report. A special thanks to Puan Zuraihana Ahmad Zawawi that acted as my lecturer supervisor for guiding me throughout the process, whose help, stimulating suggestions and encouragement, helped me to coordinate my project especially in writing this report.

I would like to acknowledge with much appreciation to the facility manager of Menara TH Tun Razak, Encik Zunnasri for giving me an opportunity to do and internship and learning in this scope. Also gratitude to the head of technical team, the technical department staff whose guiding me and teach me detail knowledge on building maintenance

Last but not least, a big thanks to my family and friend which help me to go through the process of internship.

TABLE OF CONTENT

TITLE	PAGE
Declaration by Students and SV	
Acknowledgement	i
Table of contents	ii
List of Table	iv
List of Figure	vi
CHAPTER 1 : THE DETAILS OF COMPANY	
1.1 Company Background	2
1.1.1 Company Logo	4
1.1.2 Corporate Milestone	5
1.2 Building Background	6
1.2.1 Brief Information	7
1.2.2 Floor area of tenancies	12
1.2.3 List of office department	13
1.2.4 Facilities	15
1.2.5 Building Services	17
1.3 Vision & Mission	21
1.4 Organization Chart	22
1.5 Scope of Work	25
1.6 Summary	27
CHAPTER 2: LITERATURE REVIEW: PREVENTIVE MAINTENANCE & ADHOC CORRECTIVE	
2.1 Introduction of Maintenance	29
2.2 Maintenance Classification	30
2.3 Plan Preventive Maintenance	31
2.4 Corrective/ Ad-hoc Maintenance	34
2.5 Summary	37
CHAPTER 3:CASE STUDY: ADHOC CORRECTIVE & PREVENTIVE MAINTENANCE	
3.1 Introduction of Case Study	
3.1.1 Building Background	39
3.1.2 Maintenance Organizational Structure	40
3.1.3 Communication Management Plan	41
3.2 Analysis of Plan Preventive Maintenance	
3.2.1 Plan Preventive Maintenance Schedule	42
3.2.2 Plan Preventive Maintenance Achievement	50
3.2.3 Bar Chart Of Monthly Preventive Maintenance	51

LIST OF TABLES

No.	Caption of Table	Page
1.	Table 1.1: The brief information of Menara TH Tun Razak	7
2.	Table 1.2 : The list of office department	13
3.	Table 1.3: The list of facilities	15
4.	Table 1.4: The list of building services	17
5.	Table 1.5: The scope of the maintenance department	23
6.	Table 2.1: The scope of periodic maintenance	32
7.	Table 2.2: The plan preventive maintenance in Menara TH Tun Razak	33
8.	Table 2.3: The scope of repair using ad-hoc	36
9.	Table 3.1: The communication management plan	41
10.	Table 3.2: The plan preventive maintenance for mechanical system	43
11.	Table 3.3: The plan preventive maintenance for electrical system	46
12.	Table 3.4: The plan preventive maintenance for civil/ structure system	48
13.	Table 3.5: The plan preventive maintenance activity achievement	50
14.	Table 3.6: The total response time to work task	53
15.	Table 3.7: The total execution time for work task	53
16.	Table 3.8: The total work order in March 2018	54
17.	Table 3.9: The achievement of total percentage of complete and incomplete complain	62
18.	Table 3.10: The total of work order by system	63
19.	Table 3.11: The total work order by type	64
20.	Table 3.12 : The defect item No.1 (Sediment No.1)	66
21.	Table 3.13 : The defect item No.2 (Door latch No.2)	67
22.	Table 3.14: The defect item No.3 (Slippery tiles No.3)	68
23.	Table 3.15: The defect item No.4 (Concrete bump No.4)	69
24.	Table 3.16: The defect item No.5 (Damage pipe No.5)	70
25.	Table 3.17: The defect item No.6 (Damage door No.6)	71
26.	Table 3.18: The defect item No.7 (Safety walk No.7)	72
27.	Table 3.19: The defect item No.8 (Damage floor closer No.8)	73
28.	Table 3.20: The defect item No.9 (Concrete bump No.9)	74
29.	Table 3.21: The defect item No.10 (Damage pipe No.10)	75
30.	Table 3.22: The defect item No.11 (Silicone replacement No.11)	76
31.	Table 3.23: The defect item No.12 (Panel pressurization No.12)	77
32.	Table 3.24: The defect item No.13 (Fire extinguisher No.13)	78
33.	Table 3.25: The defect item No.14 (Light blow No.14)	79
34.	Table 3.26: The defect item No.15 (Damage pipe No.15)	80
35.	Table 4.1: The problem and recommendation in Menara TH Tun Razak	85