



DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA

TITLE

(REPAIR OF GROUND SETTLEMENT WORK)

MUHAMMAD SUHEIL BIN ABDUL KADIR

(2011295406)

DIPLOMA IN BUILDING SURVEYING

PRACTICAL TRAINING REPORT

DECEMBER 2013 – MARCH 2014

DECLARATION

I hereby admit that this report is the result of my own efforts, except for certain parts that are attached from sources that specified in reference chapter.

Prepared by:

.....

(MUHAMMAD SUHEIL BIN ABDUL KADIR)

Date :

Approved by:

.....

(PUAN SITI ZUBAIDAH BINTI HASHIM)

Date :

Supervising Lecturer

ACKNOWLEDGEMENT

Alhamdulillah to the Almighty for giving me the opportunity to undergo my practical training and finish this industrial training reports within the allocated time. Therefore, I would like to give my deepest appreciation and thank you to all individuals who willing to spend time giving guides, encouragement, co-operations and comments to complete this report especially to District Engineer of Public Work Department of Kerian, Tuan Haji Abdul Kadir bin Yahya and all the staffs at public work department of Kerian for accepting me to undergo my practical training here and provide guidance that really useful to me. I also would like to giving thank and appreciation to both practical training coordinator, Mr, Nor Amin Mohd Radzuan and Mohamad Ridzuan Yahya. Not forgotten special thank to my practical training supervisor Mrs. Siti Zubaidah binti Hashim. I will not forget to both my beloved parents for keep providing me strength, by boosting my morale to finish this report. Last but not least to all to all my fellow friends as they are always standing at my side and lending me hands to ease my hard time.

Thank you

ABSTRACT

This report briefly described the method involve in defining the solution to the problem caused by ground settlement. It is also described the method of construction of building apron and drainage which are the repairing work that has been made to the affected building. This report is made based in four month of experience at Public Work Department of Kerian and involvement in the project of repairing work of ground settlement problem in Sekolah Teknik Vokasional, Kerian. This report also has been divided into few chapters which included company's background and project's background. From the observations, this repairing work takes a straight forward solution which is only repairing work to the affected building compartment but there is no action taken to the ground settlement problem such as soil improvement process that could caused the problem occurring again. This report explains in detail regarding the method of construction of building apron and building drainage. During the process of repairing work, there are a few problem occurred and this report has mentioned the solution to the problem occurred. As a conclusion, this report has provided one of the solutions to the problem caused by ground settlement in Malaysia.

TABLE OF CONTENT

TITLE	PAGE
ACKNOWLEDGEMENT	i
ABSTRACT	ii
TABLE OF CONTENT	iii
LIST OF CHART	vi
LIST OF FIGURE	vi
LIST OF TABLE	vi
LIST OF PICTURE	vii
CHAPTER 1: INTRODUCTION	
1.1 INTRODUCTION	1
1.2 COMPANY BACKGROUND	3
1.3 LOGO AND DESCRIPTION	6
1.4 ORGANIZATION CHART	7
1.5 ROLES AND DUTIES	
1.5.1 Administration Division	8
1.5.2 Road Division	10
1.5.3 Electrical Division	13
1.5.4 Special Project / Corporate Division	14
1.5.5 Building Division	16
1.5.6 Maintenance Division	18
1.5.7 Quantity Surveying Division	19
1.6 ORGANIZATION POLICY	
1.6.1 Mission of Organization	20
1.6.2 Vision of Organization	21
1.6.3 Objective of Organization	21
1.6.4 Quality Policy	22
1.6.5 Safety and Health Policy	23