



DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND
SURVEYING

UNIVERSITI TEKNOLOGI MARA

THE DAMPNESS IN BUILDING

MOHAMAD SAFRI AZWADI BIN MOHAMAD

2011897518

DIPLOMA IN BUILDING SURVEYING

PRACTICAL TRAINING REPORT

NOVEMBER 2013 – MARCH 2014

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....

(MOHAMAD SAFRI AZWADI BIN MOHAMAD)

Date:

Approved By:

.....

(PN. ZURAIHANA BINTI AHMAD ZAWAWI)

Date:

THE DAMPNESS IN BUILDING

ACKNOWLEDGEMENT

First of all, thank to Allah s.w.t for the strength given to me in completing this report, I have used full of commitment, knowledge and strength to gather all the information about the case study and inspection of work and prepare the report for the course BSB 351.

I would like to attend a sincere appreciation to my Supervisor, Miss Zainahaiza Binti Zainon for giving a lot of guidance, and full of experiences in completing my practical training. Then, to Madam Azizah Binti Abdullah and Madam Suri Junita Binti Zullkeple beause they always bring me to site of maintenance and they also always teach me about maintenance in building such as how to repair any damage is our in building and what or how to do the inspection. Thanks for their hardworking, idea, cooperation, and commitment given to me in completing these inspection works.

Not forgotten, to my supervisor lecture Madam Zuraihana Binti Ahmad Zawawi for helping me on how to overcome the problem approach in completing the report. Next, thanks to the Practical Training Coordinator, Mr. Nor Amin Mohd Radzuan and Sr Mohamad Ridzuan BinYahya.

Lastly, I would like to dedicate a special thanks to my beloved family members for their invaluable support towards the completing of the report and practical training.

THE DAMPNES IN BUILDING

CONTENT

TOPICS	PAGES
CHAPTER 1: COMPANY BACKGROUND	
1.1. Introduction of Jabatan Kerja Raya (JKR)	1
1.2. Building Background	3
1.3. Mission and vision of department	5
1.4. The organization chart every development in JKR Daerah Perak Tengah	7
1.5. Policy of JKR	13
1.6. Function JKR	14
1.7. Scope of work JKR	14
1.8. Location Plan of JKR	17
CHAPTER 2: LITERATURE REVIEW	
2.1. Dampness Problem in Buildings	18
2.2. Identification of Dampness in Building	18
2.3. The types of Dampness	21
2.4. Source of Dampness	25
2.5. Effect of Dampness	25
2.6. Method to Overcome Dampness Problem	26
2.7. Maintenance works	27
CHAPTER 3: CASE STUDY	
3.1. Introduction	30
3.2. Causes of Dampness	34
3.3. Method Of Repairing Work	37
3.4. The Material That Are Used During Repairing Work	43
CHAPTER 4: PROBLEM AND RECOMMENDATION	
4.1. Problem and Recommendation	44
CHAPTER 5: CONCLUSION	
5.1. Conclusion	45
CHAPTER 6: REFERENCES	46

THE DAMPNESS IN BUILDING

LIST OF FIGURE

TOPICS	PAGES
CHAPTER 1: COMPANY BACKGROUND	
Figure 1.1: The building of JKR Daerah Perak Tengah at Seri Iskandar.	1
Figure 1.2: The logo of Jabatan Kerja Raya (JKR).	2
Figure 1.3: The front view of JKR building.	3
Figure 1.4: The rear view of JKR building.	3
Figure 1.5: The left view of JKR building.	4
Figure 1.6: The right view of JKR building.	4
Figure 1.7: The Organization Chart of Administration Development.	7
Figure 1.8: The Organization Chart of Maintenance Development.	8
Figure 1.9: The Organization Chart of Electrical Development.	9
Figure 1.10: The Organization Chart of Estimate Value Development.	10
Figure 1.11: The Organization Chart of Road Development.	11
Figure 1.12: The Organization Chart of Building Development.	12
Figure 1.13: Location of Bandar Seri Iskandar.	17
Figure 1.14: The direction to JKR Perak Tengah.	17
CHAPTER 2: LITERATURE REVIEW	
Figure 2.1: Details showing some of the causes of damp penetration.	19
Figure 2.2: The condition of dampness at the wall.	20
Figure 2.3: Have condensation on window frame.	21
Figure 2.4: Show the penetration damp at wall and ceiling.	22
Figure 2.5: Show the falling damp at wall.	23