



**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA
CAWANGAN PERAK
KAMPUS SERI ISKANDAR**

THE INSTALLATION OF WATERPROOFING SYSTEM

ELINA BINTI ILIAS
2015445548
DIPLOMA IN BUILDING SURVEYING

**PRACTICAL TRAINING REPORT
MARCH – JULY 2018**

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....
(ELINA BINTI ILIAS)

Date:

Approved By:

.....
(NADIRA BINTI AHZAHAR)

Date:

ACKNOWLEDGEMENT

Grateful to God of Almighty that managed to accomplish this report successfully on time. Although there were quite many challenges that must face and the problems during internship at Landseal Sdn.Bhd, I managed to overcome it with some helps from people that are much respect and valuable sources. Therefore, I would to take this opportunity to thank all of them for their contributions to this report.

First and foremost, I would like to express my sincere gratitude and appreciation to the lecturer, Nadira Binti Azahar and Sr. Mohd. Nurfaizal bin Baharuddin for their continuous support, advice, guidance as well as co-operation to complete this report.

Secondly, I would like to extend my love and heartfelt appreciation to the founder of Landseal Sdn.Bhd, Dr. Radha Krishnan, for this opportunity to gain experience working for the company. My special thanks also extend to Mr. Yusri Bin Haron for his generous contributions, briefings and assist me during internship.

Lastly, I would like to state my deepest gratitude to my family and friends for their advices and moral supports as well as financial supports. Not to forget their prayers to ease my works at Landseal. Moreover, to seniors and other parties that directly or indirectly involve in helping me with this internship until I can come out with a full report.

TABLE OF CONTENTS

NO.	ITEMS	PAGES
1	ACKNOWLEDGEMENT	I
	TABLE OF CONTENT	II
	LIST OF TABLE	IV
	LIST OF FIGURE	V
	LIST OF PHOTO	VI
	LIST OF CHART	VIII
	ABSTRACT	IX
2	CHAPTER 1: INTRODUCTION OF COMPANY	
	1.1 INTRODUCTION OF COMPANY	1
	1.2 INTRODUCTION OF ORGANIZATION	2
	1.3 ORGANIZATION CHART	3
	1.4 COMPANY LOGO	5
	1.5 BUILDING LOCATION	6
	1.6 COMPANY OBJECTIVE, MISSION, VISION	8
	1.7 COMPANY DATA	9
	1.8 PANEL OF ADVISOR	10
	1.9 ASSOCIATE COMPANIES	10
	1.10 THE MANAGEMENT TEAM EXPERIENCE & QUALIFICATION	12
	1.11 TRAINING DESCRIPTION	13
3	CHAPTER 2: THEORETICAL STUDY OF WATERPROOFING	
	2.1 INTRODUCTION OF WATERPROOFING	14
	2.2 DEFINITION OF WATERPROOFING	15
	2.3 TYPES OF WATERPROOFING SYSTEM	16
	2.4 METHOD INSTALLATION STATEMENT	18

ABSTRACT

An opportunity has given to fulfil an internship at Landseal Sdn.Bhd. Landseal is a company that specialise in conducting waterproofing works. Decades of experience of the founder himself, Dr. Radha Krishnan, has brought him to start a foundation of waterproofing company known as Landseal Sdn. Bhd. Along the years, the company itself has working hand-in-hand with suppliers that continuously supplying waterproofing material over decades, such as Greenseal Products (M) Sdn. Bhd. Over 300 successful projects have recorded eversince its foundation. The staffs as well play an important roles in building the company.

The method statement on how to apply the waterproofing materials is the key to a successful waterproofing system. Therefore, a supervisor needs to fully understand the application instruction. As stated in the catalogue for reference, a brief on where is suitable for a certain materials, depending on the surface condition, requirement and function. There are various of waterproofing system are to choose from.

As first task given by the supervisor, Mr.Yusri Bin Haron, a supervision by a trainee supervisor is required at a case study of construction of Audi Showroom in Setia Alam. Progression are to be made and recorded in daily report for future reference, including photos as proofs. A couple of materials are used for internal and external areas. According to architectural plans given by the main contractor, Barcon Industry Sdn.Bhd., there are 2 floors AND 2 mezzanines, 1 rooftop and 1 basement.

As others as well, the problems throughout the internship has been stated and analysed to come out with recommendations. Every chapters encounter with either lack of information, boundaries or limitations in order to gather sources for the report. Therefore, to complete the report, solutions are figured out.