

# DEPARTMENT OF BUILDING SURVEYING FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING UNIVERSITI TEKNOLOGI MARA CAWANGAN PERAK KAMPUS SERI ISKANDAR

### **INTERGRATED FINAL PROJECT (BSR330)**

#### **CASE STUDY:**

# AEON ANGGUN RAWANG, RAWANG, SELANGOR DARUL EHSAN

#### PREPARED BY:

AHMAD MU'AZ BIN AHMAD	2014616782
AZLAN BIN ABU BAKAR	2014461716
MUHAMMAD ZARIFF BIN ABDUL RAZAK	2014632134
FAHDA AMANI BINTI MOHD ROSLEY	2014203762
NURFAZIRAH BINTI SHAROM	2014883392

DIPLOMA IN BUILDING SURVEYING

SEMESTER
JUN – OKTOBER 2016

## ACKNOWLEGEMENT

First of all, we are very thankful to Allah Rabbul Izzat who gives us such power, knowledge and ability to accomplish our goals. Without His kind help, we would unable to produce this report successfully.

The success and final outcome of this assignment required a lot of guidance and assistance from many people and we extremely fortunate to have got this all along the completion of our assignment work. Whatever we have done is only due to such guidance and assistance and we would not forget to thank them. Their contributions are sincerely appreciated and gratefully acknowledged. However, our group would like to express our deep appreciation and indebtedness particularly to the following:

Sr. Wan Samsul Zamani bin Wan Hamdan for guiding and supervising us in this subject of Integrated Final Project (IFP). Her versatile knowledge in this discipline and unique teaching style has developed our knowledge and cleared many ambiguities. A lot of respect and thanks for giving us an opportunity to do this assignment and providing support which made us complete this report within the time given.

This assignment cannot be completed without the effort and co-operation from our group members. To all friends and others who directly or indirectly helping us and supported us with their assistance and guidance to do this report.

TABLE OF CONTENT	Page
ACKNOWLEDGEMENT	i
TABLE OF CONTENT	ii
LIST OF TABLE	vii
LIST OF CHART	xi
LIST OF FIGURE	xii
ABSTRACT	xxi
1.0 The Details of the Property	
1.1 Introduction and company/organization background	2
1.2 Building Background	3
1.2.1 Building Function	5
1.3 Project Brief	8
1.3.1 Building View	10
1.3.2 Adjacent Building	15
1.4 List of Major Occupants/Tenants	19
1.4.1 Ground Floor Area Tenant	20
(Gross Floor Area – GFA)	
1.4.2 First Floor Area Tenant	22
(Gross Floor Area – GFA)	
1.4.3 Anchor Tenant	24
1.5 Facilities and Building Services	25
1.5.1 Building Facilities	25
1.5.2 Building Services	28
1.6 Summary	32
2.0 Organizational / Maintenance Management	
2.1 Introduction	34
2.2 Organization Objectives	36
2.2.1 Company's Objectives	36
2.2.2 Maintenance Department Objectives	37

# **LIST OF TABLE**

Table	Page
Table 1.4.1 Tenants in Ground	21
Floor	
Table 1.4.2 Tenants in First Floor	22
Table 1.5.1 Facilities in AEON Anggun Rawang	27
Table 1.5.2.1 List of Building Services	31
Table 2.4.1 Description of Position and Scope of Works	43
Table 3.2.1 List of Company/Organization Maintenance	48
Division Vision, Mission & Objectives. (In-House)	
Table 3.2.2 List of Company/Organization Maintenance	49
Division Vision, Mission & Objectives. (Out-Source)	
Table 4.4.1.2.1 Detail of Piling	71
Table 4.4.1.5 Details of Ground Slabs	73
Table 4.4.1.3.1 <i>Detail</i> of Foundations	72
Table 4.4.4.1.1 Detail of Wall Finishes	133
Table 4.4.3.2.1 <i>Detail</i> of Floor Finishes	135
Table 4.4.3.3 Detail of Ceiling Finishes	136
Table 4.4.2.1.1 Door Column and Specification	75
Table 4.4.2.2.1 Type of Beam and Specification	76
Table 4.4.2.3.1 Type of Wall and Specification	78
Table 4.4.2.4.1 Type of Floor and Specification	79
Table 4.4.1.2.5.1 Type of Roof and Specification	82
Table 4.4.1.2.6.1 Type of Door and Specification	118
Table 4.4.2.7 Detail of Window	128
Table 4.4.2.8.1 Staircase and Specification	129
Table 4.4.2.9.1 Type of Ceiling and Specification	131
Table 4.4.3.1 Detail of Joinery Fitting	138
Table 4.5.4.1 Active and Passive Fire Protection System	144

## **ABSTRACT**

This report represent the building of the Aeon Anggun Mall Rawang as for the case study for Integrated Final Project (BSR). subject. From the first day of the visiting, it is to find the building and take the full permission to do the study work from department facilities management of Aeon Anggun Rawang's. There are tons of information that have to find and collect through a few ways regarding to the several chapters such as building background, building design, building services, maintenance management, legal aspect, and maintenance financial budget. The method to get the information is by general research, observation, took some photos as the evidence, interview session and from lecturer notes.

The building have two main floor which the ground floor and 1st floor is full with various of tenant such as Old Town White Coffee, Big Apple, Penang xpress. AEON Anggun Mall Rawang using two maintenance department which are in house and also out source. Moreover, every service is run by special skill work. Maintenance strategy was performed to observe and managed the function of the building to be in good condition, safe and comfortable for the occupants and system in the building.

AEON Anggun Rawang has 104 tenant that has been agree with the requirement that been list by the AEON Department. The contract content for the tenant and maintenance must follow the contract, if any problem happened AEON Anggun Rawang can take an action on ending the contract for example the tenant not paying the rent. Next is the regulation of AEON Anggun Rawang comply with the Uniform Building By Law 1994 (UBBL 1984), Street Drainage & Building 1974 (ACT 1974), Occupational Safety & Health 1994 (OSHA) and Electricity Supply Act 1990 (Act 447). As for the cash flow, the income of AEON Anggun Rawang gained from the allocation maintenance, tenant rental, kiosks, weighing scale machine, parking lot and massage chair. The expenditure is on the maintenance outsource, utilities, general expenditure such as office expenditures, staff salaries and network bills.