



**DEPARTMENT OF BUILDING SURVEYING  
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING  
UNIVERSITI TEKNOLOGI MARA  
SERI ISKANDAR CAMPUS, PERAK**

## **DILAPIDATION SURVEY**

**MANZURUL HASAN BIN MARZUKI**

**2012847042**

**DIPLOMA IN BUILDING SURVEYING**

**PRACTICAL TRAINING REPORT**

**DECEMBER 2014 – APRIL 2015**

## **DECLARATION**

I hereby admit that this report is the result of my own effort, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By :

.....

(MANZURUL HASAN BIN MARZUKI)

DATE :

Approved By :

.....

(SR. ZAKI SHAMSUDIN)

DATE:

---



---

## TABLE OF CONTENTS

No.	Title	Pages
1.	<b>Acknowledgement</b>	i
2.	<b>Abstract</b>	ii
3.	<b>Chapter 1: Introduction and Building Background</b>	
	1.0. Introduction of Practical Training	1
	1.1. Objective of Practical Training	2
	1.2. Objective of Practical Training Report	3
	1.3. Importance of Practical Training	4
	1.4. Scope of Work	5
	1.5. Company Background	6
	1.5.1. Company Logo	7
	1.5.2. Company Vision and Mission	8
	1.5.3. Services Provides By Amas FM	9
	1.5.4. Company Information	10
	1.5.5. Organization Chart	11
	1.5.6. Experience / Current Project 2012 - 2014	12 – 14
	1.5.7. Managing Director	15 – 16
	1.5.8. Certificates of Registration	17 – 20
4.	<b>Chapter 2: Literature View, Dilapidation Survey</b>	
	2.0. Introduction of Dilapidation Report	21
	2.1. Types of dilapidation report	22-24
	2.2. When a Dilapidation Survey Report is Required	25
	2.3. Purpose of A Dilapidation Survey	26
	2.4. Importance of Building Inspection	27
5.	<b>Chapter 3: Case Study: Dilapidation Survey of Management Office Building National Farmers Organization, Kota Damansara</b>	
	3.0. Introduction	28
	3.1. Property Information	29
	3.2. Vision and Mission	29
	3.3. Methodology Of Current Inspection Report	30
	3.4. Dilapidation Survey Report	31
	3.5. Comment and Suggestions	32

# DILAPIDATION SURVEY REPORT NAFAS, KOTA DAMANSARA

---

## ACKNOWLEDGEMENT

Assalamualaikum.

Alhamdulillah, grateful to Allah S.W.T. that finally I had finished my practical report for course BSD 351 (Practical Training) about the Dilapidation Report At Pertubuhan Peladang Kebangsaan (NAFAS) Building, Lot 1, Jalan Teknologi 3/5, Taman Sains Selangor 1, Kota Damansara, 47810 Petaling Jaya, Selangor Darul Ehsan.

First and foremost, I would like to thank both my family because they always support me and pray for my successful in my education in UiTM Sri Iskandar, Perak Darul Ridzuan. A special thanks to my dedicated supervisor, Sr. Zaki Shamsudin who always guide and advise me during the preparation of this report.

# DILAPIDATION SURVEY REPORT

## NAFAS, KOTA DAMANSARA

---

### ABSTRACT

The practical students of Diploma in Building Surveying are supposed to undergo the practical training for about 4 months starting from 1<sup>st</sup> December 2014 until 1<sup>st</sup> April 2015. Since the practical students are able to choose their own practical training places, thus, I decide to practical at AMAS FM Consultant.

This Industrial Training is one of the requirements for all eligible, final semester, graduating students of University Technology MARA (UiTM) Diploma Programs. The main objective of this practical training is to give students to exposure on a real challenging working world.

Students will be able to apply the skills that they have obtained throughout their academic years. In addition, students can enhance their knowledge and abilities at the participating companies and develop the student's intellectual, powers and ability in analyzing fact finding and investigation through relevant scientific and qualitative analysis.

This internship is also a shared social obligation for both UiTM and the companies involved. UiTM practical students will assist institutions/organizations in handling appropriate jobs. At the same time, it also allows UiTM in identifying industries' current needs, hence fulfill them. Therefore, UiTM will be able to strengthen its curriculum and produce graduates who are market-ready.