# DEPARTMENT OF BUILDING SURVEYING FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING UNIVERSITI TEKNOLOGI MARA

DEFECTS STUDY IN HIGH LEARNING INSTITUTION

# MOHAMMAD RADZI BIN MUHAMMAD (2005361931)

BACHELOR OF BUILDING SURVEYING (HONS)

OCTOBER 2008

## DEPARTMENT OF BUILDING SURVEYING FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING UNIVERSITI TEKNOLOGI MARA

### DEFECTS STUDY IN HIGH LEARNING INSTITUTION

"I hereby declare that this academic project is the result of my own research except for the quotation and summary which have been acknowledged"

STUDENT'S NAME

MOHAMMAD RADZI BIN MUHAMMAD

**SIGNATURE** 

**UITM NO** 

2005361931

DATE

**28 NOVEMBER 2008** 

#### ACKNOWLEDGEMENT

In the name of Allah, most gracious most merciful, I am thankful that, this dissertation has been finished due time as to fulfill the requirement of my Bachelor Building Surveying (Hons). In future the production of this dissertation would be as remainder of my degree years.

Upon finishing this dissertation, I would like to express my gratitude toward those who have support me in accomplish this dissertation. Especially to my supervisor, En Ellemy Iskandar for his help and advice, without his guideline I would not be able to complete the task given also to all lecturers in Bulding Surveying Department, UiTM Shah Alam.

Not forgotten to my loving family especially my parents and all my friends for never ending wonderful support. The memories shall always remain in my mind.

Lastly, not forgotten my pleasure thank you to all parties either directly or indirectly that's involved In this dissertation.

Thank you,

en	I'liuj	i •
INTI	RODUCTION	
1.1	Introduction	1
1.2	Research Background	2
1.3	Issue of the Topic/ Problem Stateme	ent 3
1.4	Objective	4
1.5	Scope of Dissertation	5
1.6	Methodology of Study	6
1.7	Chapter Organization and Synopsis	9
		PAGI
t tri	ERATURE REVIEW	
2.1		11
2.1		11
	Maintenance in High Learning Institution  Definition of Defect	13
2.3		
	$oldsymbol{arepsilon}$	14 17
	2.3.2 Agencies Causing Deterioration	
	2.3.3 Common Building Defects	23
ВА	APT111M <sup>r</sup> ^	
BAC	KGROUNG OF CASE STUDY	
3.1	National University of Malaysia (UKN	M) 30
	3.1.1 Location Plan National University of Mal	aysia 32
	3.1.2. Residential Colleges in UKM	33
	3.1.3 Collage Ibrahim Yaakub	35
	3.1.4 Collage Burhanuddin Helmi	36
	3.1.5 Defects in Residential Collages	38

#### **CHAPTER 1**

#### INTRODUCTION

#### 1.1 Introduction

High learning institution is an education place for all students who wanted to continue their studies. The function of this high learning institution is to give appropriate education for the students according to their choices of each individual course. The high learning institutions have offer education such as certificate level, diploma, bachelor, master and PHD. There are several High Learning Institutions in Malaysia namely, University Technology of Mara, University Malaya and University Putra Malaysia

Accommodation building is important for the students at all universities especially for those who are far from the university. The accommodation building is a place for student to stay and to revive their lesson together with their friends. So the maintenance of this building is important for their safety and comfortable factor.

The whole universities has many facility buildings such as the administration offices, lecturer rooms, workshop rooms, libraries, cafes, lab computer and security rooms and other facilities such as the mosque, fields, halls and garden area. All this facilities is an asset for the university and it should be in good condition.