

DEPARTMENT OF BUILDING

UNIVERSITI TEKNOLOGI MARA

(PERAK)

Defects Inspection in Historical Building at Lembaga Getah Malaysia

Prepared by:

AZNA NUR QISTINA BINTI AZHAR

2019295644

ACKNOWLEDGEMENT

This case study has provided me a new knowledge and ideas to understand the condition of a building. I would like to acknowledge and give my warmest thanks to my supervisor Puan Nurul Elani Binti Mohd Nawi who make this work possible. Her guidance and advice carried me through all the stages of writing my case study report in my internship. I would also like to give my gratitude to Jasa Sendi (M) SDN BHD staff for letting my defense be an enjoyable momentum, and for a brilliant comments and suggestion.

I am grateful for Allah for guiding me through and enlightening my path by giving me enough patience and persistence to do this case study with optimum and confidence.

To my lecturer supervisor Dr Nor Asma Hafizah Binti Hadzaman for the endless support, kind and understanding spirit during out intern.

I'm gratitude for my family and relatives who in one way or another share their support either morally, financially and physically. Thank you.

To my friend and classmate whose challenges and productive critics, especially in and out past semester, have provided new ideas to work.

I am also thankful for the reference author which their name couldn't be disclosed, but i want to acknowledge and appreciate their help and transparency during research. Their information had helped me complete this case study.

Thank you so much.

ABSTRACT

Maintenance is an activity performed to properly maintain, and repair is an activity performed to correct defects or damage present in a structure (Patil, 2019). This will discuss about the types of defects, maintenance and repair solution. The aim for this report is to restore the building to their original form of standard and to maintain equipment and construction services and structures. The method that been use in Jasa Sendi (M) SDN BHD is observing the defect such as crack, gap, dampness and etc., the defect will be classified with a unit risk. Jasa Sendi (M) SDN BHD classified the defect risk by using BARIS assessment. Another method is creating a plan for the building. This report is focusing on the defect and maintenance for a building based on the safety guideline. It will create a safety environment for the client and other people.

Table of Contents

CONTENTS	PAGE NO
Acknowledgements	4
Abstract	5
Table of Contents	6
List of Tables	8
List of Figures	9
CHAPTER 1.0. INTRODUCTION	11
1.1. Background of Study	
1.2. Objectives	
1.3. Scope of Study	
1.4. Methods of Study	
1.4.1. Document Review	
CHAPTER 2.0. COMPANY BACKGROUND	16
2.1. Introduction of Company	
2.2. Company Profile	
2.3. Organization Chart	
2.4. List of Project	
2.4.1. Completed Project	
2.4.2. Project in Progress	
CHAPTER 3.0. Defects Inspection in Historical Building at	27
Lembaga Getah Malaysia	
3.1. Introduction of Defects Inspection in Historical	
Building at Lembaga Getah Malaysia	
3.2. Project Background	
3.2.1. Project Detail	
3.2.2. Project Information	
3.2.3. Parties Involved	
3.3. Methods of Inspection	
3.3.1 Preliminary Works	
3.3.2. Physical Works	

CHAPTER 1.0

INTRODUCTION

1.1. Background of Study

Building inspection survey are a means of assessing the condition of property in detail and include a thorough inspection. While this isn't the only type of survey for homeowners, a building survey is the most common, especially for household customers (Really Moving, 2020).

Surveys are generally conducted to help homeowners understand the condition of a property, identify risks, and potential costs that may be required in order for them to develop appropriate repair or maintenance plans. You can also prepare for individual homeowners, homebuyers, or real estate portfolio investors for guidance on future investments (Really Moving, 2020). Inspection is done after receiving request for quotation, the inspection is done during site visit.

1.2.Objectives

- I. To identify the method of inspection for defects in historical building.
- II. To determine types of defects in historical building.
- III. To identify the element contribute to defects in historical building.

1.3.Scope of Study

The study is carried out located at Lembaga Getah Malaysia, Jalan Ampang. The building is a historical building surrounding the building with the rainforest in Malaysia. The main study focus of this case study is the inspection that need to be done to the building. Hence, the studied is about the reason for the defect in the building. Also, the studied conclude the method and tools that need to be