CASE STUDY OF POWER FAILURE AT DEWAN AGONG TUANKU CANSELOR UNIVERSITI TEKNOLOGI MARA MALAYSIA

This thesis is presented in partial fulfillment for the award of the Bachelor of Engineering (Hons) Electrical

Of

FACULTY OF ELECTRICAL ENGINEERING UNIVERSITI TEKNOLOGI MARA MALAYSIA



MUHAMAD ZULHALMI BIN MOHMMAD

ANUAR

2011696564

Faculty of Electrical Engineering UNIVERSITI TEKNOLOGI MARA 40450 SHAH ALAM, SELANGOR DARUL EHSAN

ACKNOWLEDGEMENT

Alhamdulillah. Thank to the almighty Allah S.W.T. giving me the opportunity to live until now and also for His kindness give opportunity to complete this project progression as required completing my study in UiTM Shah Alam for Bachelor of Engineering (Hons.) Electrical (EE221).

I would like to thank and acknowledge to Mr. Ir. Hj. Harizan bin Che Mat Haris, lecturer in Faculty of Electrical Engineering as my supervisor for his guidance on the project research and also for his advices and positive comments that encorage me to complete the project. I also would like to thank Mr. Halmi Abbas, the Electrical engineer of UiTM's Facilty Unit for his kindness and willingness to cooperate in giving some information, data and sharing the experience regarding the power failure incident. And also i would like to thank Mr. Fazli, the Related Technician of Dewan Agong Tuanku Canselor (DATC) for his technical support in doing the research.

In addition, thanks to everyone that involved directly or indirectly in finishing the project research whether in terms of advice, opinion, criticizes knowledge, and motivation. Finally, special thanks to my parents and siblings for their noble and moral support from the beginning of the project until the project able to be complete within the period.

ABSTRACT

This project research attempts to investigate the power failure incident at Dewan Agong Tuanku Canselor (DATC) of Universiti Teknologi Mara (UiTM) Shah Alam due to the overload factor. In this project research, a simple calculation on the overload or over current condition has been carried out. The calculations are depending on the kilowatt demand of mechanical load during the UiTM's 78th convocation ceremony at DATC. The study on UiTM Shah Alam's electrical distribution system have been carried out in order to know the flow of electricity from the main supply of Tenaga Nasional Berhad (TNB) until it reached to DATC. Other than that, discussion and analysis also have been carried out based on the overload calculation result in purpose of to prove the overload is the factors that cause the power failure incident at DATC.

TABLE OF CONTENTS

DECLARATION	i
APPROVAL	ii
ACKNOWLEDGEMENT	iii
ABSTRACT	iv
TABLE OF CONTENTS	v
LIST OF FIGURES	vii
LIST OF TABLES	ix
LIST OF ABBREVIATIONS	X
CHAPTER 1: INTRODUCTION	
1.1 BACKGROUND OF STUDY	
1.1.1 Power failure	1
1.1.2 Reliability of distribution	2
1.2 PROBLEM STATEMENT	
1.2.1 Problem identification	3
1.2.2 Significant of study	9
1.3 OBJECTIVES	10
1.4 SCOPE OF WORK	10
1.5 THESIS ORGANIZATION	11
CHAPTER 2: LITERATURE REVIEW	
2.1 ELECTRICAL DISTRIBUTION SYSTEM	12
2.2 THEORITICAL BACKGROUND OF POWER FAILURE	15
2.3 EXAMPLE OF POWER FAILURE CASES	15
2.4 FACTOR OF POWER FAILURE	
2.5 RESTORATION PLANNING AND TYPICAL METHOD TO ENSURE CO POWER SUPPLY	
CHAPTER 3: METHODOLOGY	
3.1 FLOW CHART	24
3.2 PROBLEM IDENTIFICATION	
3.3 SITE VISIT	
3.4 ANALYSIS PROCESS	
3.4.1 First analysis	
3.4.2 Second analysis	
3.4.3 Third analysis	

CHAPTER 4: RESULT AND DISCUSSION
4.1 RESULTS ON OVERLOAD FIGURE
4.2 OVERLOAD CALCULATION RESULT
4.3 DISCUSSION AND ANALYSIS
4.3.1 Ion meter limitation
4.3.2 Data obtained
CHAPTER 5: CONCLUSION
5.1 THE STUDY ON ELECTRICAL DISTRIBUTION SYSTEM IN UITM SHAH ALAM . 57
5.2 THE INVESTICGATION ON OVERLOAD FACTOR AS THE MAIN CAUSE TO THE POWER FAILURE OCCUR AT DATC
5.3 THE DISCUSSION AND ANALYZATION ON THE POWER FAILURE OCCUR AT DATC
CHAPTER 6: RECOMMENDATION FOR FUTURE WORK
REFERENCES
APPENDICES
Appendix A: Ion meter specification63
Appendix B: Contractor work permission form65
Appendix C: Turnitin Plagiarism Test67
Appendix D: Technical Paper