

**UNIVERSITI TEKNOLOGI MARA  
FACULTY OF ARCHITECTURE, PLANNING AND SURVEY  
INTERIOR ARCHITECTURE DEPARTMENT**

**OCTOBER 2009**

This research project is prepared

by

**NIK MOHD FAEEZUL BIN NIK YUSOFF  
2006125255**

titled

**REPORT ON PROPOSED UPGRADING & NEW INTERIOR DESIGN SCHEME OF CHERY CENTER FOR  
WENG FATT MOTOR SDN BHD AT 205, JALAN RAJA PERMAISURI BAINUM (JALAN KAMPAR), 30250  
IPOH, PERAK.**

Accepted as a part of the requirement of Diploma in Interior Design

Report Supervisor : \_\_\_\_\_

Ms Wan Hafizayati Wan Hassan

Report Coordinator : \_\_\_\_\_

Mr. Muhammad Suhaimi Musa

Programme Coordinator : \_\_\_\_\_

Assoc. Prof. Mohd Sabrizaa Abd. Rashid

## **ABSTRACT**

The final project for Diploma in Interior Design is manifestation about the student understanding in all interior project aspect that had been learn from the basic to the presentation for propose design. For the final project, the upgrading for Chery Center had been choose at 205, Jalan Raja Permaisuri Bainum (Jalan Kampar), 30250 Ipoh, Perak. With the new 3S Center, hopes that it will upgrade the images of Chery and widen the Chery market while providing a good services. The theme and the concept that will be apply on both space "interior and exterior" is to shown the esthetic value and the prestige of Chery. Several research had been done to make the project more achives for this final project, among the research include the site analysis, research method such interview the client, observing, case study and surveying. All the research been done is to identified the existing issue and problem that occur. All the information that had been gathered will be apply with the purpose to get one good design and compatible with the Chery Cooperate image, neither the function nor the esthetic value. The new approachent concept and the modern image will be apply to get new concept and image compatible and can be shown in design and merge with Chery identity.

<b>ABSTRACT</b>	<b>i</b>
<b>PENGHARGAAN</b>	<b>ii</b>
<b>CONTENT</b>	<b>iii</b>
<b>TABLE OF FIGURE</b>	<b>iv</b>
<b>TABLE OF PICTURE</b>	<b>v</b>

<b>CONTENT</b>	<b>PAGE</b>
<b>1.0 INTRODUCTION</b>	<b>1</b>
1.1 Definition	1
1.2 Research Aim	2
1.3 Research Objective	2
1.4 Research Methodology	3
1.5 Research Method	4
1.5.1 Observation	4
1.5.2 Interview Client	4
1.5.3 Case Study	4
1.5.4 Client / Project Requirement	4
1.5.5 Internet	5
1.5.6 Choosing Site	5
1.6 Research Problem	5
1.7 The Research Important	5

<b>2.0</b>	<b>CLIENT'S</b>	<b>6</b>
2.1	General Background	7
2.1.1	Client Background	8
2.1.2	Chery Culture	9
2.2	Organisation Chart	10
2.3	Mission And Vision	11
2.3.1	Vision	11
2.3.2	Mission	11
2.4	Cooperates Image	11
2.4.1	Logo	11
2.4.2	Product	12
<b>3.0</b>	<b>SITE ANALYSIS</b>	<b>15</b>
3.1	Key Plan	17
3.2	Location Plan	18
3.3	Site Plan & Site Orientaion	19
3.4	Landmark	20
3.5	Building Analysis	21
3.5.1	Interior Condition	21
3.5.2	Photo Exterior	23
3.5.3	Structure	25
3.5.4	Finishes	27
3.5.4.1	Wall	27
3.5.4.2	Floor	29

3.5.4.3	Ceiling	31
3.5.4.4	M&E Services	32
3.5	Working Drawing	34
<b>4.0</b>	<b>CASE STUDY</b>	<b>39</b>
4.1	Study Case 1	41
4.1.1	Nasrom Sdn. Bhd. Kota Bharu	41
4.1.2	The existing space in Nasrom	41
4.1.3	Traffic Flow in Nasrom	46
4.1.4	Case Study Research	46
4.2	Study Case 2	47
4.2.1	Proton Edar Showroom	47
4.2.2	Existing space in Proton Edaran	47
4.2.3	Traffic Flow in Proton Edaran	51
4.2.4	Case Study Research	51
4.3	Study Case 3	52
4.3.1	Volkswagen Sdn. Bhd	52
4.3.2	Existing space in Volkswagen Sdn. Bhd.	52
4.3.3	Traffic Flow in Volkswagen Sdn. Bhd.	56
4.3.4	Case Study Research	56
4.4	Case Study Summary	57