



DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING & SURVEY
UNIVERSITI TEKNOLOGI MARA

A STUDY OF COMMON DEFECT AT BRITISH COLONIAL
BUILDING

This academic project is submitted in partial fulfillment of the requirement for the
Bachelor of Building Surveying (Hons.)

MOHD FAUZAN BIN HUSAINI

2008753773

BACHELOR OF BUILDING SURVEYING (HONS)

JANUARY 2010 – NOVEMBER 2010

ABSTRACT

The dissertation is to study about common defect at British colonial building and scope of study is in Klang Valley. British colonial building have a unique architectural styles and design and also has a heritage value for the country. This building from era colonial can be says give an impact for surrounding another thing, to shown the British authority as a big colonial authority and economy. The purpose a lot of colonial building is impliment a design style is to shown the architecture style and its not only come from British, but this design styles is influences from other country such as India and China.

In this study, the objectives of this dissertation will be set first. The objective of this dissertation is to focusing on identify defect are common occur at British colonial building. From this objective, details informations about detail of British colonial building in Malaysia, types of defect, common causes of defect is occur and effect of defect if no remedial action are being explained based on the literature review in chapter two. Then, research methodology in chapter three is discuss about a continuous steps to complete this dissertation.

Besides, on chapter four, it is focus on case studies. Four case studies has selected which all of building are located at Klang Valley. The case study building is at Keretapi Tanah Melayu Headquarters, Masjid Jamek Kuala Lumpur, Coliseum Theatre and Federal Territory Syarie Court. At the next chapter is discuss about analysis of data from questionnaires and interviews survey. Finally, the conclusion and recommendations of this study will be showed for future study.

TABLE OF CONTENTS

1.0	INTRODUCTION	
1.1	General Review	1
1.2	Problem Statement	2
1.3	Objectives Of Study	3
1.4	Methodology	3
1.5	Scope And Limitation Of The Study	3
1.6	Research Methodology	5
1.7	Summary Of Chapter	6
2.0	LITERATURE REVIEW	
2.1	Colonial Building	8
2.1.1	Overview	8
2.1.2	Introduction of British Colonial Building	8
2.1.3	A Conservation British Colonial Building	10
2.1.4	Overview of Architecture Design at British Colonial Building in Malaysia	11
2.1.4.1	Moorish Style	12
2.1.4.2	Tudor Style	13
2.1.4.3	Neo – Classical Style	13
2.1.4.4	Neo – Gothic Style	15
2.1.5	Classification of British Colonial Building	16
2.1.5.1	Forts / Military	16
2.1.5.2	Churches / Mosque	16
2.1.5.3	Palaces	17
2.1.5.4	Clocks Towers	17
2.1.5.5	Prisons	18
2.1.5.6	Government Office	18
2.1.5.7	Institutional and Commercial	19
2.1.5.8	Residential	19
2.1.5.9	School	19
2.1.5.10	Railways Stations	20
2.1.5.11	Hotels and Guest Houses	20
2.1.5.12	Miscellaneous Buildings / Monuments	21
2.1.6	Conservation Bodies for Historical Building in Malaysia	21
2.1.6.1	Official Conservation Committees	21

2.1.6.2	Private Societies	22
2.1.6.3	Charitable Trust	23
2.2	Defect	20
2.2.1	Definition of Building Defect	24
2.2.2	Nature of Building Defect	24
2.2.3	Common Causes of Defect in Building	25
2.2.4	Agencies Causing Defect and Deterioration in Building	27
2.2.4.1	Solar Radiation	28
2.2.4.2	Moisture	29
2.2.4.3	Biological Agencies	30
2.2.4.4	Gaseous Constituents and Pollution of Air	30
2.2.4.5	Ground Salts and Water	31
2.2.4.6	Manufactured Products	32
2.2.4.7	Juxtaposition of Materials and Components	32
2.2.5	A Common Remedial Action for Defect at Building	33
2.3	Defects In Colonial Building	36
2.3.1	Introduction of Defect in Colonial Building	37
2.3.2	Type of Defect in Colonial Building	38
2.3.2.1	Fungal Stain / Harmful Growth	38
2.3.2.2	Erosion of Mortar Joints	39
2.3.2.3	Peel of Paint	39
2.3.2.4	Defective Plaster Rendering	40
2.3.2.5	Cracking of Walls / Leaning Walls	40
2.3.2.6	Defective Rainwater Goods	41
2.3.2.7	Decayed Floorboards	42
2.3.2.8	Inserts or Termites Attack	42
2.3.2.9	Roof Defects	43
2.3.2.10	Dampness Penetration through Wall	44
2.3.2.11	Unstable Foundations	44
3.0	RESEARCH METHODOLOGY	
3.1	Introduction	46
3.2	Data Collections	46
3.3	Data Analysis	47
3.4	Result	49

4.0	CASE STUDY	
4.1	Overview of Case Study	52
4.2	Case Study 1: Headquarters Keretapi Tanah Melayu Berhad (KTMB), Kuala Lumpur	52
4.2.1	Building Background	52
4.2.2	Design and Architecture Style at Headquarters KTMB	54
4.2.3	Conservation Work Done in Headquarters KTMB, Kuala Lumpur	56
4.2.4	Common Defect in KTMB Headquarters Building	57
4.2.4.1	Settlement at Building Apron	58
4.2.4.2	Unwanted Plant and Fungus Growth	59
4.2.4.3	Peeling and Flaking of Paint	60
4.2.4.4	Corrosion	61
4.2.4.5	Building Cracks	62
4.2.4.6	Dampness	63
4.3	Case Study 2: Masjid Jamek, Kuala Lumpur	
4.3.1	Building Background	65
4.3.2	Design and Architecture Style at Masjid Jamek	66
4.3.3	Conservations Work Done in Masjid Jamek, Kuala Lumpur	67
4.3.4	Common Defects in Masjid Jamek, Kuala Lumpur	68
4.3.4.1	Settlement	69
4.3.4.2	Peeling and Flaking of Paint	69
4.3.4.3	Unwanted Plant and Fungus Growth	70
4.3.4.4	Building Cracks	71
4.3.4.5	Decay	72
4.3.4.5	Corrosion	73
4.4	Case Study 3: Coliseum Theatre	74
4.4.1	Building Background	74
4.4.2	Design and Architecture Style at Coliseum Theatre	75
4.4.3	Conservation Work Done at Coliseum Theater	76
4.4.4	Common Defect at Coliseum Theatre	77
4.4.4.1	Peeling and Flaking of Paint	78
4.4.4.2	Fungus and Algae Growth	79
4.4.4.3	Dampness	80
4.4.4.4	Blockage at Drainage System	80