

BUILDING SURVEYING DEPARTMENT
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
MARA UNIVERSITY OF TECHNOLOGY

PROBLEMS IN ACHIEVING MAINTENANCE SERVICE STANDARD
IN FOUR (4) STAR HOTEL

This dissertation is submitted in partial fulfillment of the requirement for the
Bachelor In Building Surveying (Hons)

PREPARED BY : NOOR SHAZARINA BINTI HASNAN
SESSION : FINAL YEAR (2002/2003)

TABLE OF CONTENTS

	Page
ACKNOWLEDGEMENT	i
TABLE OF CONTENTS	iii
LIST OF TABLE	vii
LIST OF FIGURE	x
LIST OF APPENDIX	xiv
LIST OF PHOTOGRAPHS	xiv
CHAPTER 1 : INTRODUCTION OF DISSERTATION	
1.0 Introduction	1
1.1 Definition of topic	2
1.2 Scope of research	3
1.3 Issue	3
1.4 Objective of study	3
1.5 Methodology of study	4
1.6 Hypothesis	4
1.7 Conclusion	5

CHAPTER 2 : HOTEL BUILDING AND MAINTENANCE NEEDS

2.0	Introduction	6
2.1	Classification Of Hotel	7
2.2	Maintenance Of Hotel	
2.2.1	Maintenance Defined	8
2.2.2	Classification Of Maintenance	11
2.2.3	Maintenance Department	17
2.2.4	Maintenance Programmes	19
2.2.5	Maintenance Manual	22

CHAPTER 3 : STANDARD OF MAINTENANCE FOR BUILDING SERVICES IN HOTEL.

3.0	Introduction	27
3.1	Building Services In Hotel	27
3.2	Maintenance Service Standard In Hotel	30
3.3	Division of Maintenance Service Standard	31
3.4	Seven Keys Areas For Establishing Maintenance Standard	33

CHAPTER 4 : CASE STUDY

4.0	Introduction	53
4.1	Scope Of Research	53
4.2	Grand BlueWave Hotel	
4.2.1	Hotel Overview	54

4.2.2	Facilities Provided	56
4.2.3	Building Services Provided	58
4.2.4	Hotel Maintenance Standard	72
4.3	Quality Hotel	
4.3.1	Hotel Overview	84
4.3.2	Facilities Provided	85
4.3.3	Building Services Provided	86
4.3.4	Hotel Maintenance Standard	91
4.4	Prescott Hotel	
4.4.1	Hotel Overview	100
4.4.2	Facilities Provided	100
4.4.3	Building Services Provided	102
4.4.4	Hotel Maintenance Standard	105

CHAPTER 5 : DATA ANALYSIS

5.0	Introduction	117
5.1	Limitation Of Study	117
5.2	Data Collection	118
5.3	Data Analysis	119
5.4	Analysis of the problems that may occur in achieving the maintenance standard expected at Grand BlueWave Hotel, Shah Alam.	121

5.5	Analysis of the problems that may occur in achieving the maintenance standard expected at Quality Hotel, Shah Alam.	139
5.6	Analysis of the problems that may occur in achieving the maintenance standard expected at Prescott Hotel, Klang.	156
5.7	Analysis of the occupants opinion about the maintenance quality and service standard of the hotel.	173
5.8	Conclusion from the analysis for each hotel.	178
5.9	Overall Analysis	185

CHAPTER 6 : RECOMMENDATION AND CONCLUSION

6.0	Introduction	190
6.1	Recommendations	190
	6.1.1 Training Programme	191
	6.1.2 Maintenance Scheduling	194
6.3	Conclusion	201