



**DEPARTMENT OF BUILDING SURVEYING  
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING  
UNIVERSITI TEKNOLOGI MARA  
CAWANGAN PERAK  
KAMPUS SERI ISKANDAR**

**BUILDING CONDITION ASSESSMENT: PWD QUARTERS JALAN BRUSEH**

**MUHAMMAD IRFAN HAKIMI BIN WIRA  
(2013752033)  
DIPLOMA IN BUILDING SURVEYING**

**PRACTICAL TRAINING REPORT  
JUNE 2016 – SEPTEMBER 2016**

**DEPARTMENT OF BUILDING SURVEYING  
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING  
UNIVERSITI TEKNOLOGI MARA  
CAWANGAN PERAK  
KAMPUS SERI ISKANDAR**

**BUILDING CONDITION ASSESSMENT: PWD QUARTERS JALAN BRUSEH**

**JUNE 2016 – SEPTEMBER 2016**

This practical training report is fulfilment of the practical training course.

PREPARED BY : MUHAMMAD IRFAN HAKIMI BIN WIRA  
SUPERVISING LECTURER : SR DR ALIA ABDULAH SALEH

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....  
(MUHAMMAD IRFAN HAKIMI BIN WIRA)

Date:

Approved By:

.....  
(SR DR ALIA ABDULAH SALEH)

Date:

## Table of Content

No.	Content	Page number
1.	ANKNOWLEDGEMENT	
2.	CHAPTER 1: ORGANIZATION OVERVIEW	1
	1.1 INTRODUCTION	1
	1.2 COMPANY BACKGROUND	2-4
	1.2.1 PUBLIC WORK DEPARTMENT VISION AND MISION	5
	1.2.2 PURPOSE AND AIMS	6
	1.2.3 OBJECTIVE	7-9
	1.2.4 LIST OF PUBLIC WORK DEPARTMENT'S BRANCHES	10
	1.3 PUBLIC WORK DEPARTMENT VISION AND MISSION	11-13
	1.4 PUBLIC WORK DEPARTMENT ORGANIZATION CHART	14
	1.4.1 CAWANGAN PERANCANGAN ASET BERSEPADU (CPAB)	
	1.4.2 CPAB ORGANIZATION CHART	
	1.5 SCOPE OF WORK	
	1.5.1 PORTFOLIO MANAGEMENT UNIT	
	1.5.2 STATE FACILITY MANAGEMENT UNIT	
	1.6 LOCATION PLAN	
3.	CHAPTER 2: THEORITICAL STUDY/LITERITURE REVIEW	15
	2.1 BUILDING CONDITION ASSESSMENT INTRODUCTION	15
	2.2 PROCESS OF INSPACTION IMPLEMENTATION	16-19
	2.2.1 INSPECTION FLOW CHART	20
	2.2.2 DETAILS OF THE PROCESS	
	2.3 SCOPE OF WORK	
4.	CHAPTER 3 : CASE STUDY	21
	3.1 PROPERTY INFORMATION	21
	3.2 DEFECT ANALYSIS	22
	3.3 BARISS ASSESSMENT	23-31
	3.4 DEFECT SHEET	32-64
	3.5 COMMON DEFECT OCCURS IN QUARTERS	65-70
	3.5.1 FUNGUS STAIN AND HARMFUL GROWTH	
	3.5.2 PEELING PAINT	

## **ACKNOWLEDGEMENT**

First, I would like to thanks to Almighty ALLAH S.W.T for the blessing and the chance that give me to finish the practical training and finally, able to finish the task that given to us on time.

This assignment is the result of four month effort in practical training in JKR Perak. Firstly I would like to thank supervisor Sr Dr Alia Abdulah Saleh for her guidance with a useful knowladge in finishing this report. It means a lot to me.

Not forgotten, our special thanks to my practical training supervisor Mr. Azlan Bin Abdul Aziz , workers of Cawangan Perancangan Aset Bersepadu JKR Negeri Perak because give me many experience than cannot get any where. I also want to thank them because give me the information to finish this report.

Last but not least , I would like to express my gratitude to my parents who give me non-stop support and spirit.