



**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA
CAWANGAN PERAK
KAMPUS SERI ISKANDAR**

**DILAPIDATION SURVEY
(COMPLETE)**

**IKHWAN HAKIMI BIN MAT ZUKI
2013389921
DIPLOMA IN BUILDING SURVEYING**

**PRACTICAL TRAINING REPORT
JUNE 2016 – SEPTEMBER 2016**

**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA
CAWANGAN PERAK
KAMPUS SERI ISKANDAR**

(DILAPIDATION SURVEY)

JUNE 2016 – SEPTEMBER 2016

This practical training report is fulfilment of the practical training course.

PREPARED BY : IKHWAN HAKIMI BIN MAT ZUKI

SUPERVISING LECTURER : SR DR MOHD AZIAN ZAIDI

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....
(Ikhwan Hakimi bin Mat Zuki)

Date:

Approved By:

.....
(Sr. Dr. Mohd Azian Zaidi)

Date:

Acknowledgement

I would like to take this opportunity to thank Sr. Anwar Bin Haron, Sr Rusalan Affendy bin Arshad, En Muhammad kamal bin Ahmad, Cik Aisyah Humairah binti Razlan and Pn. Hafilzah binti Roslan for allowing me to make the practical training, teach me to do the work, whether in the office or outside the office, help me in doing project work structure, building condition survey, CIDB program, tenders, measurement and bill quantities.

besides, I also want to thanks to UiTM allow me to study here from the beginning of the semester. to lecturers who teach or not. My supervisor during practical Sr. Dr Mohd Azian bin Zaidi, Sr Amin bin Mohd Radzuan visiting during practical and Sr Mohd Nurfaaisal bin Baharuddin as Practical Training Coordinator.

finally, thank you very much to my parents who gave their time, energy and money and help me in all issues.

LIST OF CONTENTS

Chapter 1

| | | |
|-------|------------------------------|---|
| 1.0 | Company Background | 1 |
| 1.1 | Company Information | 3 |
| 1.2 | Vision | 3 |
| 1.3 | Location Pelan | 4 |
| 1.4 | Scope of Work | 4 |
| 1.4.1 | Service Provide | 5 |
| 1.5 | Organization Company | 7 |
| 1.6 | Scope of Report | 7 |
| 1.7 | Introduction of Dilapidation | 7 |
| 1.8 | Purpose | 9 |
| 1.9 | Objective | 9 |

Chapter 2

| | | |
|-------|---------------------------------------|-----|
| 2.0 | Introduction | 10 |
| 2.1 | Flow Chart of Dilapidation Survey | 10 |
| 2.2 | Conformation on Client Instruction | 11 |
| 2.2.1 | Surveyor Declaration | 12 |
| 2.2.2 | Certificate of Building Inspection | 13 |
| 2.2.3 | Declaration of Inspection | 14 |
| 2.3 | Preliminaries Survey | 15 |
| 2.3.1 | Property Information During Practical | 15I |
| 2.3.2 | Property Background | 15 |
| 2.3.3 | Description of Property | 15 |
| 2.3.4 | Location | 17 |
| 2.3.5 | Tools and Equipments | 18 |
| 2.4 | The Inspection | 21 |
| 2.4.1 | Assessment of Defect | 22 |