



**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA
CAWANGAN PERAK
KAMPUS SERI ISKANDAR**

**BUILDING CONDITION SURVEY REPORT
AT LOT 2, JALAN HANG LEKIU,
BANDAR HILIR
MELAKA
(COMPLETE)**

**SYARIFAH NUR ADLIN BINTI SYED ABDUL WAHED
(2015891882)
DIPLOMA IN BUILDING SURVEYING**

**PRACTICAL TRAINING REPORT
MARCH – JULY 2018**

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....
(SYARIFAH NUR ADLIN BINTI
SYED ABDUL WAHED)

Date:

Approved By:

.....
(PUAN AIDA AFFINA BINTI ABD
GHANI)

Date:

ACKNOWLEDGEMENT

Alhamdulillah I have completed my industrial training for subject BSR360 for this semester. First of all, I feel thankful to the almighty for the blessing given to me to complete this industrial training report. I am thankful to my Academic Coordinator Industrial Training (BSR360), SR. Mohd Nurfaizal Baharuddin and my Academic Supervisor, Puan Aida Affina Abd Ghani, who has helped me a lot in completing this report.

The internship opportunity I had with Anjung Teknik was a great chance for learning and professional development. Therefore, I am grateful for having a chance to meet so many wonderful people and professionals who led me through this internship period.

Bearing in mind previous I am using this opportunity to express my deepest gratitude and special thanks to Tuan Hj. Kamarudin Bin Md Said, Manager of Anjung Teknik who in spite of being extraordinarily busy with his duties, took time out to hear, guide and keep me on the correct path and allowing me to carry out my project at their esteemed organization and extending during the training.

CONTENT

ACKNOWLEDGEMENT.....	I
CONTENT.....	III
LIST OF PHOTO	VII
LIST OF TABLE	XI
LIST OF FIGURE	XIII
LIST OF CHART	XIII
ABSTRACT.....	XIV
CHAPTER 1.0: ORGANIZATIONAL BACKGROUND.....	1
1.1 Introduction.....	1
1.2 Company Background	2
1.3 Company Profile	3
1.4 Organisation Chart.....	5
1.5 Scope of Work	6
1.6 Location Plan	7
1.7 List of project.....	9
1.7.1 Interior Design Works.....	9
1.7.2 Conservation Works.....	14
1.8 Summary	41
CHAPTER 2: CONSERVATION HERIITAGE BUILDING / BUILDING CONDITION ASSESSMENT.....	42
2.1 Introduction.....	42

ABSTRACT

This report is about all the general and technical information about the company that have been selected. This report has 4 chapter which included all the general information and technical information about building condition survey at Lot No.2, Jalan Hang Lekiu, Bandar Hilir, Melaka. This report can be used as a reference for Heritage Architectural Building Surveys before construction works, HABS (Stage 1)

The first chapter in this report is detail of information of the company. In this chapter, all the general information about the background of the company and the organization company. This chapter include the scope of work and location of the company. It also have list of project that have been done by the company.

The second chapter give out information about the conservation heritage building and building condition survey. This chapter provided the information about the detailing the conservation works and how to do the building condition survey based on the secondary resources.

The third chapter is a case study which is located at Lot No.2, Jalan Hang Lekiu, Bandar Hilir, Melaka. The condition survey were conducted in the area and the building defect has been stated in this report.