



**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA
CAWANGAN PERAK
KAMPUS SERI ISKANDAR**

DILAPIDATION SURVEY AT ALAMANDA, PUTRAJAYA
BY
QLASSIC STANDARD WORK

MOHD RIZAL BIN ZULKARNAINE
2012912147
DIPLOMA IN BUILDING SURVEYING

**PRACTICAL TRAINING REPORT
DECEMBER 2015 – APRIL 2016**

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....
(MOHD RIZAL BIN ZULKARNAINE)

Date:

Approved By:

.....
(SR PUAN MARIATY BT MOHD BAHARI)

Date:

TABLE OF CONTENT

NO.	CONTENT	PAGES
1	ACKNOWLEDGEMENT	I
2	LIST OF FIGURES	II
3	LIST OF TABLES	III
4	CHAPTER 1 : INTRODUCTION	1
	1.1 BACKGROUND OF COMPANY	1
	1.2 COMPANY ORGANIZATION	2
	1.3 SCOPE OF WORK	3
	1.4 LOCATION OF COMPANY	5
5	CHAPTER 2 : LITERATURE REVIEW	
	2.1 Introduction	6
	2.1.1 Approved Standard	6
	2.1.2 Qualified Person (Qp) Or Principal – Submitting Person (Psp)	6
	2.1.3 Component	7
	2.1.4 Element	7
	2.2 Objective Of Qlassic	7
	2.3 Assessment Approach	8
	2.4 Components To Be Assessed	9
	2.5 Quality Standard For Architectural Works	11
	2.5.1 Internal Finishes - Floor	
	2.6 Quality Standard For Architectural Works	14
	2.6.1 Internal Finishes – Internal Wall	
	2.7 Quality Standard For Architectural Works	18
	2.7.1 Internal Finishes – Ceiling	
	2.8 Quality Standard For Architectural Works	20
	2.8.1 Internal Finishes – Door	
	2.9 Quality Standard For Architectural Works	22
	2.9.1 Internal Finishes – Window	
	2.10 Quality Standard For Architectural Works	25
	2.10.1 Internal Finishes – Fixtures	

ACKNOWLEDGEMENT

Bismillahirrahmanirahim

Firstly, Alhamdulillah thanks to Allah S.W.T for giving me a health and strength to prepare a report entitle ‘ Dilapidation Survey at Alamanda, Putrajaya base on QLASSIC standard on my practical training in Canaan Building Inspection SDN BHD according to the schedule and time set successfully.

On this occasion, I wish to express my gratitude to SR. Joshua Kang Wee Ling for giving me the opportunity to undergo my industrial training at Canaan Building Inspection and also to my supervisor Sir. David Chung for giving me the guidance and trust during my industrial training at the company.

This gratitude also goes to my supervisor lecturer, SR Pn. Mariaty Bt Mohd Bahari, who is willing to provide guidance and tutoring during the process of the preparation this report.

Also thanks to both of my parents that always support me from the started to the end. To my friends who were willing to help and inspire as well as to the parties involve directly or indirectly , thousands of thanks for giving me encouragement throughout the learning and the completion of this report

Lastly, I am Forever indebted to them who has trusted in me and for that I am forever grateful. Thank you very much everyone.

ABSTRACT

First and for most, this practical training report is about the dilapidation survey for Alamanda shopping mall, Putrajaya. This dilapidation survey is carried just for (visual and measurement) architecture work only which is appointed by Pembinaan Ikhlas-Merak SDN BHD. This practical training report have been divided by several part which is company background, literature review, case study, problem, and recommendation.

In the first chapter will introduce to my company background in detail which is contain the background of the company, location on maps and also logo of company. I also put the organisation chart of the company and also the another activity of the company.

In this report, have literature review which is introduce about QLASSIC in detail that related with dilapidation survey. It is contains the definition of the QLASSIC, objective , scope of work and assessed of QLASSIC. In definition, there are description of the approved standard, QP & PSP, Component and Element, component to be assessed and assessed approach

After that, I start with my case study which is the dilapidation survey at Alamanda, Persint 1, Putrajaya, in this chapter have a detail on the location of our site and highlighted on the construction site and also dilapidation survey. There is also a brief about our client profile. The report that I have done is by area that means, I put all the defect by location for example common area, office and owner unit.