

**DEPARTMENT OF BUILDING SURVEYING  
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING  
UNIVERSITI TEKNOLOGI MARA  
CAWANGAN PERAK  
KAMPUS SERI ISKANDAR**

Projek Penswastan Lebuhraya Bertingkat Sg Besi – Ulu Klang (SUKE) –  
(Infrastructure Industrial Area & Used Car)

**DECEMBER 2016 – MARCH 2017**

This practical training report is fulfilment of the practical training course.

PREPARED BY : ABDUL MUHAIMIN BIN HUSAIN

SUPERVISING LECTURER : SR AMIR FASHA MOHD ISA

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....  
(ABDUL MUHAIMIN BIN HUSAIN)

Date:

Approved By:

.....  
(SR AMIR FASHA MOHD ISA)

Date:

## **ACKNOWLEDGEMENT.**

Alhamdulillah, I finally finished my practical training report completely. Special thanks to my supervisor of University lecturer SR Amir Fasha for my practical training as their sacrifice to help and guide me from the step of practical training until the end of practical training. I would like to thanks to SR Puan Hafsah Bt Yahaya for supervise me on doing thing report and not forget to my dearest family that always support me along this journey.

A part of this session, I would express my appreciation to my company which is Hytechempire Consultant Sdn. Bhd. or familiar known as HYTECH for their kindness and trust giving on me and also give me a chance to learn more, not only at theory like we study in classroom but also practical in my doing job. I want to say a lot of thank you to Puan Hafsah Yahaya for letting me and give me a change to follow their team go to site.

Thanks to our friends and family for support and give an advice to finish this practical project report. They have helped us in many way such us giving us guideline and information how to create an excellent report.

## **ABSTRACT.**

This report explains on how to do dilapidation survey. Topic that I choose for this report is infrastructure at the industrial area and used car area Sg Besi, Selangor. This dilapidation survey needs to do before new construction start. This report produced refer for undergone practical training in HYtechEMPIRE CONSULTANCY SDN.BHD, Bandar Seri Putra, Kajang, Selangor.

This report divided into six chapters that starting with company profile. Then it follows with theoretical review about dilapidation survey for infrastructure. After that, case study during practical training. Then, problem and recommendation follow by conclusion and lastly references.

This report concludes with conclusion and recommendation that can be ensured during undergone practical training. In conclusion, this report able to explain overall on certificate of fitness.

## **TABLE OF CONTENT**

NO	CONTENT	PAGES
1	Acknowledgment	1
2	Abstract	2
3	Table of Content	3-4
4	I. Company Profile –  A. Company Background B. Basic Info About Hytechempire Consultancy Sdn.Bhd C. SSM Certification D. MOF Certification E. Company Vision F. Company Mission G. Organization Chart H. Skop of Work Hytechempire Consultancy Sdn.Bhd I. Track Record – Building Surveys J. Track Record – Building Consultancy K. Track Record – Course & Training L. Location Plan M. Logo Hytechempire Consultancy Sdn.Bhd	5-18
5	CHAPTER 1: THEORETICAL STUDY/ LITERATURE REVIEW  1.0 Introduction of Dilapidation Survey 1.1 When a Professional Dilapidation Survey is Required 1.2 Purposes of Dilapidation Survey 1.3 Method of Dilapidation Survey 1.4 Process of Dilapidation Survey 1.5 Advice for Landlords	19-34