



**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA
CAWANGAN PERAK
KAMPUS SERI ISKANDAR**

**CASE STUDY:
MAINTENANCE OF WATER TANK
AT APARTMENT LAGUNA BIRU**

**MUHAMMAD AZWAN BIN MOHTAR
(2014689078)
DIPLOMA IN BUILDING SURVEYING**

**PRACTICAL TRAINING REPORT
DECEMBER 2016 – MARCH 2017**

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....

(MUHAMMAD AZWAN BIN MOHTAR)

Date: 3/4/2017

Approved By:

.....

(SR NAZHATULZALKIS JAMALUDIN)

Date:

ACKNOWLEDGEMENT

Assalamualaikumwb.

Here, I would like to thanks to Allah s.w.t where give strength to complete this report completely. Alhamdulillah, I collect all the data in the better ways.

Firstly, I would like to thank the parties involved, who have given encouragement to me who help and give strength to me during my industrial training within 4 months.

Secondly, I would like to thanks to Encik Sr. Abdul Mutalib Aman Shah MISM, MIVMM the director of Amas FM Consultant Sdn. Bhd. for giving an opportunity to be a part of staff and not forget to my supervisor Cik, Siti Emiliya Sarida Che Musa, Facility Manager at Amas FM Consultant Sdn. Bhd. who has given a lot of tutoring and guidance to me on how to work in that company successfully.

Thirdly, I would like to thank to my supervisor during this semester, Cik Sr. Nazhatul zalkis Jamaludin. Who has given a lot of guidance in completing the task. Alhamdulillah, with the advice of her I was able to prepare the report BSR 360 successfully.

Lastly, I would like to acknowledge with much appreciation, the crucial role of University Teknologi MARA in providing us the platform and facilities for students to learn and obtain crucial information. Moreover, we would like to

ABSTRACT

Practical Training (BSR 360) is the main core subject for the Final Year Student of Diploma in Building Surveying, in UiTM Perak. This course was consisting of 8.0 credit hours, semester 6. Practical Training refers to work experience that is relevant to professional development prior to graduation. One of the requirements for the students of Diploma in Building Surveying to complete the program is the students must complete at least 14 weeks of Practical Training. The purpose of the report is to add the knowledge about the maintenance water tank for water supply. This report describe the method of the maintenance of water tank include the component of water tank.

TABLE OF CONTENT

ACKNOWLEDGMENT.....i

ABSTRACT.....ii

CHAPTER 1.0 COMPANY BACKGROUND.....1

 1.1 INTRODUCTION OF COMPANY.....3

 1.2 KEY PLAN, LOCATION PLAN AND SITE PLAN.....4

 1.3 COMPANY VISION AND MISION.....6

 1.4 SCOPE OF WORK.....7

 1.5 COMPANY INFORMATION.....9

 1.6 ORGANIZATION COMPANY.....10

 1.7 EXPERIENCE/CURRENT 2012-2016.....13

 1.8 DIRECTORS INFORMATION.....17

CHAPTER 2.0 LITERITURE REVIEW OF WATER TANK.....21

 2.1 PLUMBING WORKS FOR WATER SUPPLY SYSTEM.....22

 2.1.1 Water supply comes from one of two basic sources.....23

 2.1.2 Water system supply direct and indirect sytem.....24

 2.2 INTRODUCTION OF WATER TANK.....25

 2.3 TYPES OF WATER TANK.....27