



UNIVERSITI TEKNOLOGI MARA

**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA**

DILAPIDATION SURVEY OF BASEMENT FOR DEMOLISHED WORK

**RADEN HEEDHIR BIN ABDUL RAHMAN
2012106039
DIPLOMA IN BUILDING SURVEYING**

**PRACTICAL TRAINING REPORT
JUNE 2015 – OCTOBER 2015**

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....

(RADEN HEEDHIR BIN ABDUL RAHMAN)

Date:

Approved By:

.....

(MOHD ZAKI SHAMSUDIN)

Date:

ACKNOWLEDGEMENT

Firstly, I want to thank to my family which the one that supporting me from the start of the practical training until the end of making the practical report. My family has support me in various way such as giving encouragement in every problem come, in expenses I need to produce the report and also helping me in solve all the problem come to me.

Secondly, I want to thank to my lecturer supervisor Mr. Mohd Zaki Shamsudin for all thing I need in my time from practical training and preparing the practical report. Mr. Zaki really help me in a lot of thing such as giving information, guiding me in making proper report and helping me in solve all the problem. He also provides me with a lot of new knowledge for me to overcome any situation in my new environment.

Thirdly, I really want to thank to Mr. Steven Pang Chin Chooi which is the director of K&P Cove Consultancy because giving me an opportunity to get a lot of new knowledge. I also want to thank to all the senior staff at the workplace who willingly to help and guide me in various way.

Next, I want to thank to all my friends who helping me in making and preparing this report in many way.

Lastly, I want to thank again to all of people that help me in making, preparing and finishing this practical report. This report will not complete if they not helping and without them this report will not complete successfully.

TABLE OF CONTENT

CONTENT	PAGES
LIST OF FIGURE	iv
LIST OF CHART	vi
LIST OF TABLE	vi
ABSTRACT	vii
OBJECTIVE OF STUDY	viii
SCOPE OF STUDY	ix
CHAPTER 1 COMPANY PROFILE	
1.0 ORGANISATION CHART FOR K&P COVE CONSUTANCY SDN BHD COMPANY	2
1.1 COMPANY PROFILE	3
1.2 COMPANY BACKGROUND	5
1.3 COMPANY LOCATION	6
1.4 COMPANY SERVICES	7
1.5 JOB PROFILE	10
CHAPTER 2 – LITERATURE REVIEW	
2.0 DEFINITION OF BASEMENT	17
2.1 TYPE OF BASEMENT	18
2.2 FUNCTION OF BASEMENT	23
2.3 INTRODUCTION OF DILAPIDATION SURVEY	25
2.4 PURPOSE OF DILAPIDATION SURVEY	26
2.5 SCOPE OF DOING INSPECTION WORK	27

ABSTRACT

Practical report is made about the process I have been through for 4 month of practical training. This report is about all things I done from the first day I come to work at the practical training place until the last day of my practical training.

This report consists of four parts which is the company background, literature review, case study and problem and recommendation. Every part of the report has they own point which discussing for the topic. The first part is tell about the company background and second part is about the general view about the knowledge regarding the case study. The third part is about the case study for the report which is about the dilapidation survey of basement. Lastly, about the problem encounter when the survey is done and the solution for the problem to make sure the work done smoothly.

The case study about dilapidation survey which in mainly done by me at practical training with a few project. This experience helps me in overcome all the problem come and solve it by time. I also learn a lot of thing from the practical training as various new things I encounter. This helps me to become more responsible and ready to go to the new environment.