



DEPARTMENT OF BUILDING SURVEYING,
FACULTY OF ARCHITECTURE,
PLANNING AND SURVEYING.



اَوْبُوْرَسِيْتِيْ تِيْكَوْ لُوْ كِيْ مَارَا
UNIVERSITI
TEKNOLOGI
MARA

DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA

**CONDITION SURVEY ON ROAD WORK FOR PRE & POST 2 APARTMENT
SERVICE BLOCK WITH 39 FLOOR DEVELOPMENT PROJECT**

IZZAH KAMILAH BT SHAHARUDDIN

2012808688

DIPLOMA IN BUILDING SURVEYING

PRACTICAL TRAINING REPORT

DISEMBER 2014 – APRIL 2015

This practical training report is fulfillment of the practical training course.

PREPARED BY:

SUPERVISING LECTURER:



DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....

()

Date:

Approved By:

.....

()

Supervising Lecturer

Date:



No	Content	Page
1	Chapter 1: Company Profile	1-20
	1.0: Company profile	2
	Company policies	3
	1.1: Organization Chart for Cove Consultancy	4
	1.2: Department Chart for Cove Consultancy	5
	1.3: An overview of Practical training	6-8
	1.4: K&P Cove Consultancy details	9
	1.5: K&P Cove Consultancy location	10
	1.6: View of Company's Building	11-12
	1.7: K&P Cove Consultancy services	13-15
	1.8: Job Profile	16-19
	1.9: Building management work	20
5	Chapter 2: Literature review of condition survey at road work	21-37
	2.0: introduction of road	22
	2.1: Types Of road	23-28
	2.2: Function of Road	29
	2.3: Introduction Of Dilapidation	30-31
	2.4: Purpose of Dilapidation survey	32-33
	2.5: Standard of Procedure (SOP) for dilapidation Survey of K&P Cove consultancy	34-37
6	Chapter 3: Case Study	38-67
	3.0 Introduction of case study	39-40
	3.1 Background of Case Study.	41-42
	3.2: Type of road that had been inspection.....	43-45
	3.3 Inspection equipment.	46-50
	3.4 Defects on Road	51-61
	3.5 Summary of defect on roads	62-67
	Chapter 4: Problem and Recommendation	
7	4.0: Problem and recommendation	68-75
		69-75
8	Chapter 5: Conclusion and References	76-82
	5.0 Conclusion	77-80
	5.1 References	81-82
9	5.2 Appendices	83-115



Chapter 1:

Company Profile



Chapter 2:

Literature Review Of Condition Survey at Road Work