

**UNIVERSITI TEKNOLOGI MARA
CAWANGAN PERAK
FAKULTI SENIBINA, PERANCANGAN DAN UKUR
JABATAN SENIBINA DALAMAN**

JULAI 2005 – NOVEMBER 2005

Adalah disyorkan bahawa kajian akhir ini disediakan oleh :

MOHAMAD SYAHRUL BIN ARIFF SHAH

2002142733

bertajuk

LAPORAN TESIS

CADANGAN PENGUBAHSUAIAN AUTO BAVARIA (M) SHOWROOM

DI NO 207, JALAN BUKIT BINTANG, 55100,

KUALA LUMPUR

Di terima sebagai memenuhi sebahagian dari syarat untuk memperolehi

Diploma Rekabentuk Dalaman

Penyelia : Cik Mawar Masri

Koordinator : En. Othman Mohd Nor

Ketua Kursus : Puan Ramiah Alwi

(Tandatangan / Tarikh)

1.1 Research Introduction

1.1.1 Design Mission

The intended mission is to create a design that :

- 1. To design an interior space for Auto Bavaria (M) showroom at No 207, Jalan Bukit Bintang, 55100, Kuala Lumpur.**
- 2. The design will create a sporty and stylish environment.**
- 3. To portray the right image that met Auto Bavaria (M) intended function, vision, mission, and objective principle.**
- 4. The value of technical design in consideration of compliance technical.**

Contents :

Acknowledgement.

Chapter	1.0	Introduction
	1.1	Research Introduction
	1.1.1	Design Mission
	1.1.2	Design Objectives
	1.1.3	Methodology
	1.2	Client
	1.2.1	Client's Background
	1.2.1.2	History Of Organization
	1.2.1.3	Client's Address
	1.2.1.4	Client's Mission
	1.2.1.5	Client's Vision
	1.2.2	Logo
	1.2.2.1	Corporate Colors
	1.2.2.2	Motto / Theme
	1.2.3	Organization Chart

Chapter	2.0	Project
	2.1	Project Introduction
	2.1.1	Client's Brief
	2.1.1.1	Area Requirement
	2.1.2	Scope of Work
	2.1.2.1	Building Interior
	2.1.2.2	Building Extension / Demolishing
	2.2	Case Study
	2.2.1	Case Study 1 (Auto Bavaria Jalan Bukit Bintang)
	2.2.1.1	Existing Space Study
	2.2.1.1.1	Interior Design
	2.2.1.1.2	Light And Ventilation
	2.2.1.2	Building Facade
	2.2.1.3	Interior Pictures
	2.2.2	Case Study 2 (Cartrade Jalan Pinang)
	2.2.2.1	Existing Space Study
	2.2.2.1.1	Interior Design
	2.2.2.1.2	Light And Ventilation
	2.2.2.2	Building Facade
	2.2.2.3	Interior Pictures

2.2.3 Case Study 3 (Traza Auto Sdn. Bhd.)

2.2.3.1 Existing Space Study

2.2.3.1.1 Interior Design

2.2.3.1.2 Light And Ventilation

2.2.3.2 Building Facade

2.2.3.3 Interior Pictures

2.2.4 Interview

2.3 Site Analysis

2.3.1 Site Location

2.3.2 Building Analysis

2.4 Site Analysis

2.4.1 Climate And Microclimate

2.4.2 Sun And Wind Orientation/ Traffic Flow

2.5 Existing Building Analysis

2.5.1 Existing Space

2.6 Research Summaries

2.6.1 Site Potential

2.6.2 Site Weakness