



UNIVERSITI TEKNOLOGI MARA

**DEPARTMENT OF BUILDING SURVEYING
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITY TECHNOLOGY MARA**

TITLE

**BUILDING CONDITION ASSESSMENT (BCA)
(JABATAN PENGANGKUTAN JALAN ALOR SETAR KEDAH)**

MOHD ALIF BIN CHE AZMI

2012655752

DIPLOMA IN BUILDING SURVEYING

**PRACTICAL TRAINING REPORT
JUNE 2015 – OCTOBER 2015**

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared By:

.....

(MOHD ALIF BIN CHE AZMI)

Date:

Approved By:

.....

(EN. WAN SAMSUL ZAMANI WAN HAMDAN)

Supervising Lecturer

Date:



ACKNOWLEDGEMENT

All the praises are for the Almighty ALLAH who grant me with His blessings, I would like to express my gratitude to all those who give me the chances to complete my 20 weeks practical programme. I would like to thank especially to Mrs. Chua Lee Hwa and Miss Siti Umami Sarah for all their assistances, guidances and great helps in all difficult times to finish my internship programme at Jabatan Kerja Raya Kedah.

I am deeply indebted to all staff of Jabatan Kerja Raya Kedah. Those help, stimulating encouragement, support, guidance and valuable knowledge to me to explore trainee in a very professional manner. I also would like to give my special thanks to my friends those enable me to complete my industrial trainee. Thanks also to Jabatan Pengangkutan Jalan Alor Setar's members on their cooperated during our inspection work.

I hope that this report will give evidences and guidance to me during the training period. It is also expected to serve as a guide and reference useful to all students, especially students of Building Surveying.

TABLE OF CONTENT

NO.	CONTENT	PAGE
1.	CHAPTER 1 : INTRODUCTION OF PRACTICAL TRAINING	
	1.1 INTRODUCTION	1
	1.2 OBJECTIVE OF INDUSTRIAL TRAINING	2
2.	CHAPTER 2 : COMPANY BACKGROUND	
	2.1 HISTORY OF JKR KEDAH	3
	2.2 COMPANY PROFILE	4-6
	2.3 LOCATION	5
	2.4 ORGANIZATION CHART	6
	2.5 LOGO OF JKR	7
	2.5.1 DESCRIPTION OF LOGO	7
	2.5.2 COLOR	8
	2.5.3 COLOR CODE	8
	2.6 FUNCTION OF JKR	9
	2.7 THE OBJECTIVE, MISSION AND VISION OF JKR KEDAH	10
	2.7.1 OBJECTIVE	10
	2.7.2 VISION	11
	2.7.3 MISSION	11
	2.8 THE OBJECTIVE OF BAHAGIAN BANGUNAN	12
	2.9 FUNCTION OF BUILDING DEPARTMENT	12
3.	CHAPTER 3 : LITERATURE REVIEW (BUILDING CONDITION ASSESSMENT)	
	3.1 INTRODUCTION	13
	3.2 SCOPE	14
	3.3 ROLE AND RESPONSIBILITIES	15
	3.4 WORK FLOW PROCESS	16-17
	3.5 PROCESS OF INSPECTION	18-24
	3.6 TOOL AND EQUIPMENT	25-26
	3.7 TYPE OF DEFECT/DAMAGE (CIVIL)	27
	3.8 TYPE OF DEFECT/DAMAGE (MECHANICAL/ELECTRICAL)	28
	3.9 CAUSES OF DEFECT	28
	3.10 THE LEVEL OF THE PHYSICAL CONDITION OF THE BUILDING COMPONENTS	29
	3.11 THE PRIORITY LEVEL OF MAINTENANCE ACTION	30
	3.12 ANALYSIS MATRIX COMPONENT LEVEL	31

CHAPTER 1: INTRODUCTION