



اَوْبُوْ سَيِّدِيْ بَاتِيْكَوْ لُوْ كِيْ مَارَا
UNIVERSITI
TEKNOLOGI
MARA

DEPARTMENT OF BUILDING SURVEYING
FALCULTY OF ARCHITECTURE, PLANNING AND SURVEYING
UNIVERSITI TEKNOLOGI MARA
PERAK

BUILDING INSPECTION FOR DILAPIDATION SURVEY

NOR FAEZAH BINTI MOHAMED LETFI

2011339969

DIPLOMA IN BUILDING SURVEY

PRACTICAL TRAINING REPORT

DECEMBER 2014 – APRIL 2015

DECLARATION:

I hereby admit that this report is the result of my own efforts, except for the certain parts that are attached from sources that specified in reference chapter.

Prepared by:

.....

()

Date:

Approved by:

.....

()

Supervising Lecturer

Date:

ACKNOWLEDGMENT

In the name of ALLAH the Almighty, the most of beneficent and the most merciful, I would like to express my deepest sense of gratitude to him that I can managed to complete this report and if not for his help and guidance for this report maybe it will be cannot be finished properly. I wish to give my appreciate to my supervisor, Sr. En Nor Amin bin Mohd Radzuan

A special thanks to En.Azraie bin Abdullah of Site Supervisor at the Sri Tinggi Sdn.Bhd. that give permission for me to do case study at Kajang (K 3-3) to get some information and data. In addition, that to the person that involve directly and indirectly to make this report to finish successfully.

Last but not least, I would like to express my sincere and heartiest thanks to Dr. Ahmad bin Ramly, a chairman of Jasa Sendi (M) Sdn.Bhd, and also my practical supervisor, Nurul Elani Binti Mohd Naw, my dearest family always give support and advice, other staff of the company and fellow my dear friends for their encouragement, support and motivation in the course of completing this report. No doubt, all of them who is my source of inspiration.

Table of Content

No.	Topic	Page
	ACKNOWLEDGEMENT	i
	LIST OF PHOTO	4 – 5
	LIST OF FIGURE	6
	LIST OF TABLE	6
	INTRODUCTION	7
	OBJECTIVE OF PRACTICAL TRAINING REPORT	8
	METHODOLOGY OF STUDY	9
1.	Chapter 1 – Introduction Of Company	10
	1.1 Introduction	11
	1.2 Company Details	12 – 13
	1.3 Company Logo And Motto	14
	1.4 Board Of Director	15
	1.5 Organization Chart	16
	1.6 Service Provided	17 - 18
	1.7 Company Founder And Consultants	19 – 20
	1.8 Location Map	21
2.	Chapter 2 – literature view	22
	2.1 Introduction of building inspection	23 – 24
	2.2 Introduction to Dilapidation Survey	25
	2.2.1 Purpose of Dilapidation Survey	26
	2.2.2 Different of Condition Survey Report and Dilapidation Survey Report	27 - 28
	2.2.3 Items required in Dilapidation Survey Report	28
	2.3 Scope of building inspection	29 – 33
	2.4 Techniques used in Building Inspection	34

CHAPTER 1

Company Profile