

# DEPARTMENT OF BUILDING SURVEYING FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING UNIVERSITI TEKNOLOGI MARA CAWANGAN PERAK KAMPUS SERI ISKANDAR

#### GRAND KAMPAR HOTEL KAMPAR

	GROUP 1		
1	AMIRUL AMMAR BIN HUZAIMI MUHAMAD HAIKAL BIN MUHAMAD	2014866064	
2	ZAIDI	2014607452	
3	MUHAMMAD AIMAN BIN AZAMI	2014651436	
4	NUR ANIS ASNEEDA BINTI MOHAMED	2014251194	
5	WAN NURSHAZWANI BINTI WARUZI	2014441618	

### **ACKNOWLEDGEMENT**

Alhamdulillah praised be to Allah, we feel thankful to Allah because with his bless, finally we finish our assignment due on time. We also feel grateful because Allah give us a chance to do research and He ease everything to us and make all easier for us to do the inspection at our case study at Grand Kampar Hotel. Without his blessing we can't finish the task.

Firstly, we would like to give big thanks to En. Saifulizan for taking his working time for helping and giving us input about Grand Kampar Hotel. We also would like to express our highest gratitude to all those who have given the assistance and cooperation in many forms whether it is in terms of physically or technically to completion of this report successfully.

Our thanks is especially dedicated to Pn. Siti Zubaidah binti Hasyim and Pn. Zuraihana binti Zawawi for the lesson that given to us. We also would like to express our appreciation for them for guide us how to manage and to settle down this assignment. Also, thank you to the owner of Grand Kampar Hotel Sdn. Bhd. that give cooperation to us to make his building as a site for us to make our integrated final project assignment.

Not to forget for our group members Amirul Ammar bin Huzaimi, Muhammad Aiman bin Azami, Muhamad Haikal bin Muhamad Zaidi, Nur Anis Asneeda bt Mohamed and Wan Nurshazwani bt waruzi which are have given full of cooperation, thank you for the commitment. Besides that, we also would like to thank the entire classmate that give us information about this assignment and help us to done this assignment successful. Also not forgetting our parents who have given a lot of moral support and encouragement. Thank you a lot of you.

May Allah bless all of your willingness to help us.

# TABLE OF CONTENT

	TOPIC	PAGE		
ACKNOWLEDGEMENT. i				
TABLE OF CONTENTii				
LIST OF FIGUREvii				
LIST OF TABLExv				
LIST OF FLOW CHARTxviii				
ABSTRACTxix				
CHAPTER 1: DETAIL OF PROPERTY				
1.0	INTRODUCTION	2		
1.1	BUILDING BACKGROUND	3		
1.2	LOCATION PLAN	4		
1.3	PROJECT BRIEF	5		
1.4	LIST OF TENANT	6		
1.5	FACILITIES AND UTILITIES	9		
1.6	SUMMARY	14		
CHAPTER 2: ORGANIZATION MAINTENANCE MANAGEMENT				
2.1	INTRODUCTION	16		
2.2	ORGANIZATION OBJECTIVE	16		
2.3	ORGANIZATION STRUCTURE	17		
2.4	SCOPE AND RESPONSIBILITY	18		
2.5	SUMMARY	20		
CHAPTER 3: MAINTENANCE POLICY, PLANNING AND PROGRAMME				
3.1	INTRODUCTION	22		
3.2	MAINTENANCE ORGANIZATION DIVISION, MISSION			
	AND PLANNING	23		
3.3	MAINTENANCE POLICY AND QUALITY POLICY	25		
3.4	MAINTENANCE DIVISION STANDARD AND			
	QUALITY STANDARD	28		
3.5	MAINTENANCE PLANNING	33		
3.6	MAINTENANCE PROGRAMME	35		
3.7	SUMMARY	43		

## **ABSTRACT**

Final Integrated Project consist of Ten (10) chapter. The case study is Grand Kampar Hotel (GKH). In first chapter, it story about the building information include the building background, the building facilities and utilities and location of the building. In second chapter, there are many subject about organization of the building. In this chapter, there organization structure, scope and responsibility of maintenance department. In third chapter, it has GKH vision, mission and objective, maintenance quality and GKH planning of maintenance. In fourth chapter, it about building design and their technology. From sub-structure until superstructure, 14 building services and external work has been inform in this chapter. This chapter also has been inform about special technology that Grand Kampar Hotel used for maintenance. In fifth chapter, it about building condition assessment. In this chapter, it inform the 15 defect has been detect on building survey of building that already nine (9) years old. The defect retification cost also has in this chapter. In sixth chapter, it inform about maintenance strategy for the future. In seventh chapter, it about legal aspect. It has inform about the building service contract agreement and service level agreement. It also consisted of Uniform Building by Law 1984, Act 133, Street, Drainage & Building 1974, Occupational Safety & Health 1994 (Osha) and Electricity Supply Act 1990 (Act 447). In eighth chapter, it inform about the financial of maintenance. Also have forecast budget from 2015 until 2018. In this chapter also have the analysis of financial. In ninth chapter, it inform about building problem and recommendation to fix that. And last chapter, it inform about the whole conclusion.

## 1.0 INTRODUCTION

Grand Kampar Hotel is delay by their own company. The name of the company is Grand Kampar Hotel Sdn. Bhd. The owner of the company is Tan Sri Hew Sin Thong which is the main manager of Grand Kampar Hotel. Grand Kampar Hotel is a 3-star deluxe hotel. Grand Kampar Hotel is an impressive Spanish architecture and European style building, which is the fastest growing township in the area. Grand Kampar Hotel features have 155 rooms in five categories. Which is Standard Deluxe, Executive Deluxe, Triple Deluxe, Family Suite and Executive Suite. All the rooms are equipped with modern facilities for your comfortable accommodation in Kampar. Grand Kampar Hotel has high-speed WIFI connection. It's available at every floor area. Grand Kampar Hotel has free limited parking. Grand Kampar Hotel is the ideal venue for any banqueting, conferencing or wedding events. The function rooms offer modern amenities ranging from boardroom size to large group of up to 550 people. Grand Kampar Hotel also has their own restaurant, which is Chinese restaurant and Bright international restaurant.



Figure 1.1: Grand Kampar Hotel